

# NM OIL CONSERVATION

ARTESIA DISTRICT

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

OCT 24 2014

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
RECEIVED accordance with 19.15.29 NMAC.

## Release Notification and Corrective Action

**OPERATOR** ☒ Initial Report ☐ Final Report

**Name of Company:** COG Operating LLC **229137** **Contact:** Robert McNeill  
**Address:** 600 West Illinois Avenue, Midland TX 79701 **Telephone No.** 432-230-0077  
**Facility Name:** BKU Central Tank Battery SWD (BKU221) **Facility Type:** Facility

**Surface Owner:** Fee **Mineral Owner:** Fee **API No.** N/A 30-015-27764

## LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	24	17S	29E	N/A	N/A	N/A	N/A	Eddy

32.8117 Latitude N32' 49.180 Longitude W104' 01.569 104.0262

## NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 45 bbls PW	Volume Recovered: 40 bbls PW
Source of Release: Pump failure	Date and Hour of Occurrence: 10-10-2014 12:00 pm	Date and Hour of Discovery: 10-10-2014 12:00 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher - OCD	
By Whom? Amanda Trujillo	Date and Hour: 10-16-2014 8:01 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

The release was caused by a plunger on a triplex pump failing. Vacuum trucks were dispatched to remove any standing fluids and the pump was replaced.

Describe Area Affected and Cleanup Action Taken.\*

The impacted area was with in the bermed facility in an area approximately 10'x30'. Concho will have the spill site sampled to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

## OIL CONSERVATION DIVISION

Signature:	Approved by Environmental Specialist:	
Printed Name: Amanda Trujillo	Approval Date: 10/27/14	Expiration Date: NA
Title: Senior Environmental Coordinator	Conditions of Approval:	
E-mail Address: atrujillo@concho.com	Attached <input type="checkbox"/>	
Date: October 24, 2014 Phone: 575-748-6940	Remediation per O.C.D. Rules & Guidelines	

\* Attach Additional Sheets If Necessary

RECEIVED  
SUBMIT REMEDIATION PROPOSAL NO  
LATER THAN: 11/27/14

229.2565