<u>District 1</u> 1625 N. French Dr., Hobbs, NM 88240 District III
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Form C-141 Revised August 8, 2011

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action	
nAB1431855535	OPERATOR
Name of Company: BOPCO, L.P. 200737	Contact: Tony Savoie
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220 Facility Name: PLU-CVX-JV-BS #030H	Telephone No. 575-887-7329 Facility Type: Exploration and Production
Surface Owner: Federal Mineral Ow	
LOCATION OF RELEASE	
Unit Letter Section Township Range Feet from the N	North/South Line Feet from the East/West Line County
C 3 258 31E 330	North 1440 West Eddy
Latitude <u>N 32.165638</u> Longitude <u>W 103.768037</u>	
	RE OF RELEASE 297 1. Saude 278
Type of Release: Emissions from burning crude oil	Volume of Release: 307 bbls crude oil burned during the fire. Volume Recovered: 268 bbls of crude oil was still in the tanks after the fire.
Source of Release: Two five hundred barrel flow back frac tanks	Date and Hour of Occurrence: 11/13/14 at 8:10 a.m.
Was Immediate Notice Given?	Approximately 8:10 a.m. If YES, To Whom:
☐ Yes ☐ No ☐ Not Requ	Randy Dade with the NMOCD Jim Amos with the BLM
By Whom? Tony Savoie	Date and Hour: 11/13/14 at 8:43 a.m. OCD and 8:46 a.m. BLM
Was a Watercourse Reached? ☐ Yes ☒ No	If YES, Volume Impacting the Watercourse. NW OIL CONSERVATION ARTESIA DISTRICT
If a Watercourse was Impacted, Describe Fully.*	NOV 1 4 2014
Describe Cause of Problem and Remedial Action Taken.*	
While performing normal operations of producing into and removal of product from the temporary flow back tanks, a fire was notice of one of the frac tanks. The process was shut down, 911 was called, and equipment and personnel were move to a safe place away from the fire. Fire departments were dispatched to the site from Malaga, Loving, and Otis. The fire was extinguished at 12:12 p.m. Emergency personnel remained on-site cooling down equipment until it was safe for normal operations personnel to assess the damage.	
Describe Area Affected and Cleanup Action Taken.* There was no hydrocarbon product impact to the surface of the well pad. There were containments around all of the frac tanks; however most of them were destroyed by the heat of the fire. The only fluid observed after the fire was extinguished was fresh water and foam. It was noted that there was no sheening visible on the water. The damaged tanks will be removed, new containments will be constructed around the replacement tanks. A complete summary report will be submitted after the investigation has been completed.	
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.	
	OIL CONSERVATION DIVISION
Signature: / Gry Danne	
Printed Name: Tony Savoie	Approved by Environmental specialist Mile Branches
Title: Waste Management and Remediation Specialist	Approval Date:
E-mail Address: tasavoie@basspet.com	Conditions of Approval:
Date: 11/14/14 Phone: 432-556-8730	Remediation per O.C.D. Rules & Guldelines
Attach Additional Sheets If Necessary	ATER THAN: 18 14 14 2 2599