

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141

Revised August 8, 2011

DEC 15 2014

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1435036006

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: BOPCO, L.P.	Contact: Tony Savoie
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: PLU-CVX-JV-PB #008H	Facility Type: Exploration and Production

Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-42630
------------------------	------------------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section 32	Township 25S	Range 31E	Feet from the 2180	North/South Line North	Feet from the 660	East/West Line East	County Eddy
-------------	---------------	-----------------	--------------	-----------------------	---------------------------	----------------------	------------------------	----------------

Latitude N 32.087867 Longitude W 103.793453

NATURE OF RELEASE

Type of Release: Produced water	Volume of Release: 90 bbls. Produced water	Volume Recovered: approximately 10 bbbls.
Source of Release: Frac tank containment	Date and Hour of Occurrence: 12/11/14 time unknown	Date and Hour of Discovery: 12/11/14 at 11:30 a.m. 12/12/14
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? E-mail to the NMOCD and BLM 12/12/14 T. Savoie	
By Whom? Tony Savoie	Date and Hour: 12/11/14 at 1:31 p.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

The produced water was spilled by contract crew improperly dismantling and cleaning the frac tank containment around the frac tank farm. All of the free standing fluid was recovered with a vacuum truck.

Describe Area Affected and Cleanup Action Taken.\*

The spill impacted approximately 19,000 sq.ft. of caliche well pad. The spill are will be cleaned up once the frac tanks and equipment have been removed from the area. The spill will be cleaned up in accordance to the NMOCD and BLM remediation guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>Tony Savoie</u>	OIL CONSERVATION DIVISION	
Printed Name: Tony Savoie	Signed By: <u>M. L. Bernal</u> Approved by Environmental Specialist:	
Title: Waste Management and Remediation Specialist	Approval Date: 12/16/14	Expiration Date:
E-mail Address: tasavoie@basspet.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 12/15/14	Remediation per O.C.D. Rules & Guidelines	

Phone: 432-556-8730

\* Attach Additional Sheets If Necessary

SUBMIT REMEDIATION PROPOSAL NO  
LATER THAN: 1/16/15

2RP-2661