NM OIL CONSERVATION

ARTESIA DISTRICT

N. French Dr., Hobbs, NM 88240

strict II

811 S. First St., Artesia, NM 88210

District III
1000 Rio Brazos Road, Aztec, NM 87410

District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

DEC 1 7 2014

Form C-141 Revised August 8, 2011

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Rebrit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

			Rel	ease Notifi	catio	n and C	orrective A	action	
NAB1435334641						OPERATOR X Initial Report Final Report			
Name of C	ompany X	TO Energy		5380		Contact John Robinson			
Address 500 West Illinois, Suite 100 Midland TX 79701 Facility Name ADU 816 (AVALON DELAWARE INTERPRETATION)						Telephone No. 575-441-5199			
Facility Na	ime ADU	816 (H	VALON 1	DELAWARE L	KTIUL	Facility Typ	oe Injection We	<u> </u>	
Surface Owner Mineral Owner						API No. 3001524696			
	•		·	LOC	ATIO	N OF RE	LEASE		
Unit Letter	Section 5	Township 21S	Range 27E	Feet from the 563	North	/South Line North	Feet from the 560	East/West Line East	County EDDY
	· .		La	titude		Longitud	le		
	·	· · · · · · · · · · · · · · · · · · ·		NAT	CURE	OF REL			
Type of Release Oil and Produced Water						Volume of Release 5 Oil and 60 Volume Recovered None Water			
Source of Release Injection Line						Date and Hour of Occurrence Date and Hour of Discovery			
Was Immediate Notice Given?						9-27-14 7:00 am 9-27-14 7:00 am If YES, To Whom?			
X Yes No Not Required						Jeff Robertson			
By Whom? John Robinson						Date and Hour 9-27-14 3:00pm			
Was a Watercourse Reached? ☐ Yes X No						If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.*									
It a Watercou	irse was imp	oacted, Descri	be Fully.*						
		,	•				•		
Describe Cau	se of Proble	m and Remed	ial Action	Taken.*					
Corrosion on	flow line	Shut in wall							
Corrosion on	TIOW INIC.								
B. 1. A.	100 1 1	. 1 (1):	· 31		·	· · · · · · · · · · · · · · · · · · ·	······································		
Describe Area	Affected at	na Cleanup A	ction lake	71. ₹				••	
Pasture . No	action taken	yet							
•									
regulations all public health o should their of	operators as or the environerations have ment. In add	re required to nament. The a ve failed to ad dition, NMOC	report and acceptance lequately in D accepta	or file certain re of a C-141 repor nvestigate and re	lease no t by the mediate	tifications and NMOCD mar contamination	I perform correcti ked as "Final Rep n that pose a three	ve actions for re- port" does not rel at to ground wate	suant to NMOCD rules and leases which may endanger ieve the operator of liability r, surface water, human health compliance with any other
Signature:	July	Relie	M			OIL CONSERVATION DIVISION			
Printed Name. John Robinson						Approved by Environmental Specialist, Le Brandeste			
Title: Maintenance Foreman						pproval Date: Expiration Date:			
E-mail Address: john_robinson@xtoenergy.com						onditions of Approval: Attached			
Date: 10-1-14	L		Phone: 579	5_441_5100					1 1

* Attach Additional Sheets If Necessary