

NM OIL CONSERVATION

ARTESIA DISTRICT

DEC 18 2014

Form C-141
Revised August 8, 2011

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
conformance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NA1500439675

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Linn Operating Inc. 2109334	Contact E.L. Gonzales
Address 2130 W Bender Blvd Hobbs, NM 88240	Telephone No. 575-738-1739
Facility Name Keel West Water flood Plant (closest well H.E. West B 27)	Facility Type Water flood Plant

Surface Owner Federal	Mineral Owner	API No. (closest well 3001505074)
-----------------------	---------------	-----------------------------------

LOCATION OF RELEASE

Unit Letter N	Section 04	Township 17S	Range 31E	Feet from the 660	North/South Line South	Feet from the 1980	East/West Line West	County Eddy
------------------	---------------	-----------------	--------------	----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude 32.85815 Longitude -103.87611

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 159 bbls	Volume Recovered 130 bbls
Source of Release FG- pipeline	Date and Hour of Occurrence 12/04/2014	Date and Hour of Discovery 12/04/2014 0400
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

Got called out drove to location. Found header #3 with 0 psi. Produce water inside dike. Closed valve on header #3. Stopped leak. Got H pump running again.

Describe Area Affected and Cleanup Action Taken.*

vac truck picked up ground spill

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: E.L. Gonzales	Approved by Environmental Specialist 	
Title: Production Supervisor	Approval Date:	Expiration Date:
E-mail Address: elgonzales@linenergy.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 12/18/2014	Phone: 505-504-8002	

* Attach Additional Sheets If Necessary

2RP-2712