

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

0 AB1502034968 OPERATOR ☐ Initial Report ☒ Final Report

Name of Company - Devon Energy <u>6137</u>	Contact - Trae Warcup	
Address - 4134 Seven Rivers Highway	Telephone No. - (575) 748-3371	
Facility Name - Cotton Draw Unit 99	Facility Type - Oil/Gas Well Pad (Drilling)	
Surface Owner - State	Mineral Owner - State	API No. - 3001542770

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	36	24S	31E	330	North	2310	East	Eddy

32,160125 59

Latitude 32° 10' 48.651" N Longitude 103° 43' 49.551" W

103.7305-10558

NATURE OF RELEASE

Type of Release - Drilling Solids	Volume of Release - 1 bbl.	Volume Recovered - 1 bbl.
Source of Release - Solids Control Bin	Date and Hour of Occurrence - 01/15/15, 2:30 pm	Date and Hour of Discovery - 01/15/15, 2:30 pm
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

NM OIL CONSERVATION

ARTESIA DISTRICT

JAN 19 2015

RECEIVED

Describe Cause of Problem and Remedial Action Taken.*

While attempting to load an open top bin on an R360 Environmental Solutions Inc. truck, approximately 1 bbl of solids spilled onto the ground. The driver did not have a tarp installed on top for transport. The driver was instructed to inform his supervisor of the spill and have a replacement tarp sent to location before he would be allowed to leave location with the bin.

Describe Area Affected and Cleanup Action Taken.*

Area was approximately 8' x 7' x .5". All solids were shoveled up along with the affected dirt and put back in to the solids bin and disposed of.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>Trae Warcup</u>	OIL CONSERVATION DIVISION	
Printed Name: Trae Warcup	Approved by Environmental Specialist: <u>Hu Pen</u>	
Title: EHS Professional Drilling	Approval Date: <u>1/20/15</u>	Expiration Date: <u>NA</u>
E-mail Address: <u>trae.warcup@dvn.com</u>	Conditions of Approval: <u>FINAL</u> Attached <input type="checkbox"/>	
Date: 01/19/2015	Phone: 575-628-2846	

* Attach Additional Sheets If Necessary

2RP-2744