

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION
ARTESIA DISTRICT

JAN 21 2015

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.
RECEIVED

Release Notification and Corrective Action

NAB1502633538

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: BOPCO, L.P. <u>260737</u>	Contact: Tony Savoie	
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329	
Facility Name: North Indian Flats 26 Federal #1	Facility Type: Exploration and Production	
Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-27556

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	26	21S	28E	2150	North	1980	East	Eddy

Latitude N 32.452537 Longitude W 104.054648

NATURE OF RELEASE

Type of Release: Produced water	Volume of Release: 7 bbls produced water	Volume Recovered: 4 bbls produced water
Source of Release: Air Eliminator	Date and Hour of Occurrence: 1/12/15 time unknown	Date and Hour of Discovery: 1/12/15 approximately 1:17 p.m.
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? M. Bratcher, H. Patterson and Jim Amos	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* An air eliminator on the water transfer pump failed, the part was replaced.

Describe Area Affected and Cleanup Action Taken.* The spill affected approximately 450 sq. ft. of earthen containment berm around the water storage tank. Same area impacted as previous spill on 9/24/14, reference spill report #2RP-2523. The spill area will be remediated following the NMOCD and BLM guidelines for spills and releases.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>Tony Savoie</u>		OIL CONSERVATION DIVISION	
Printed Name: Tony Savoie		Approved by Environmental Specialist: <u>[Signature]</u>	
Title: Waste Management and Remediation Specialist		Approval Date: <u>1/23/15</u>	Expiration Date: <u>NA</u>
E-mail Address: <u>tasavoie@basspet.com</u>		Conditions of Approval:	
Date: <u>1/21/15</u> Phone: 432-556-8730		Remediation per O.C.D. Rules & Guidelines SUBMIT REMEDIATION PROPOSAL NO <u>2RP-2759</u>	

* Attach Additional Sheets If Necessary

LATER THAN: 2/23/15