

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141
Revised October 10, 2003

JAN 23 2015

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

RECEIVED

Release Notification and Corrective Action

NAB150 2637829

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company Yates Petroleum Corporation	OGRID Number 25575	Contact Robert Asher
Address 104 S. 4 TH Street		Telephone No. 575-748-4217
Facility Name Puppy BPP State Com. #1-Y	API Number 30-015-39483	Facility Type Battery

Surface Owner State	Mineral Owner State	Lease No. LG-5803
------------------------	------------------------	----------------------

LOCATION OF RELEASE



Unit Letter D	Section 2	Township 17S	Range 27E	Feet from the 390	North/South Line North	Feet from the 200	East/West Line West	County Eddy
------------------	--------------	-----------------	--------------	----------------------	---------------------------	----------------------	------------------------	----------------

Latitude 32.87049 Longitude 104.25573

NATURE OF RELEASE

Type of Release Oil & Produced Water	Volume of Release 9 B/O & 11 B/PW	Volume Recovered 8.5 B/O & 10.5 B/PW
Source of Release Heater Treater	Date and Hour of Occurrence 1/6/2015; AM	Date and Hour of Discovery 1/6/2015; AM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? N/A	
By Whom? N/A	Date and Hour N/A	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* Hole developed in heater treater. Vacuum truck(s) and roustabout crew(s) called.		
Describe Area Affected and Cleanup Action Taken.* An approximate area of 50' X 20' was affected within the lined/bermed battery. Remaining oil/produced water was moved to a tank at the battery, valves shut, heater repaired. Vacuum trucks recovered 95% of released oil and produced water, remaining oil/produced water entrained in impacted gravel, gravel was taken to an approved facility of disposal. Depth to Ground Water: 50-99' (approx. 50', ChevronTexaco Trend Map), Wellhead Protection Area: No, Distance to Surface Water Body: >1000', SITE RANKING IS 10. Based on battery being lined/bermed and 95% of crude oil/produced water was recovered, Yates Petroleum Corporation requests closure.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

OIL CONSERVATION DIVISION

Signature: 	Approved by District Supervisor: 	
Printed Name: Robert Asher	Approval Date: 1/23/15	Expiration Date: N/A
Title: NM Environmental Regulatory Supervisor	Conditions of Approval: Final	
E-mail Address: boba@yatespetroleum.com	Attached <input type="checkbox"/>	
Date: Friday, January 23, 2015	2RP-	

* Attach Additional Sheets If Necessary

2RP-2760