

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

AUG 30 2012

NMOCD ARTESIA

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	BOPCO, LP	Contact	Tony Savoie
Address	522 W. Mermod, Suite 704 Carlsbad, NM 88220	Telephone No.	(432) 556-8730
Facility Name	James Ranch Unit #112-H Pumping Well	Facility Type	E & P

Surface Owner State of N.M.	Mineral Owner: State of N.M.	Lease No. NM 02953-C
-----------------------------	------------------------------	----------------------

LOCATION OF RELEASE

30-015-36722

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	36	22S	30E					Eddy

Latitude N. 32.34270 Longitude W 103.82626

NATURE OF RELEASE



Type of Release	Crude oil and produced water	Volume of Release	15 bbls crude oil and 15 bbls produced water	Volume Recovered:	10 bbls total fluid
Source of Release:	Pump Jack Well Head	Date and Hour of Occurrence	4/30/12 Time unknown	Date and Hour of Discovery	4/30/12 9:00 a.m.
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	NMOCD Emergency #104		
By Whom?	Tony Savoie	Date and Hour:	4/30/12 2:49 p.m.		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* The well pressured up and blew out the stuffing box packing. The packing was replaced and the pressure problem was corrected.

Describe Area Affected and Cleanup Action Taken.* An area covering approximately 1800 sq. ft. on the caliche well pad was affected by the release. The release was remediated according to NMOCD guidelines for spill remediation. Please see the attached Remediation Summary and Site Closure Request, dated May 2012, for details of remediation activities and analytical results from confirmation soil samples.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases, which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Tony Savoie		Approved by District Supervisor: 	
Title: Waste Mgmt. & Remediation Specialist		Approval Date: 1/16/15	Expiration Date: N/A
E-mail Address: tasavoie@basspet.com		Conditions of Approval: Final	Attached <input type="checkbox"/>
Date: 8/30/12 Phone: (432) 556-8730			

2RP-1141