

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

NM OIL CONSERVATION  
ARTESIA DISTRICT

FEB 12 2015

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
conformance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1504835072		OPERATOR		<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Name of Company RKI E&P, LLC		Contact Zack Laird			
Address 210 Park Ave. - Ste. 900, OKC, OK 73102		Telephone No. 405-742-2696			
Facility Name: North Brushy Draw 35-4H		Facility Type: Oil and Gas Well			
Surface Owner: Federal		Mineral Owner: Federal		API No. 30-015-42290	



LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	35	25S	29E		175 FSL		2365FWL	Eddy

Latitude: 32.0793265 Longitude: -103.9554992

NATURE OF RELEASE

Type of Release: Oil	Volume of Release: 30Bbbs	Volume Recovered: 30Bbbs
Source of Release Tanks over ran because oil wasn't hauled	Date and Hour of Occurrence 02/12/15 - 0800hrs MT	Date and Hour of Discovery 02/12/15 - 0900hrs MT
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Heather Patterson (left VM on office line)	
By Whom? Zack Laird	Date and Hour: 02/12/15 - 1530hrs CT	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.*  Oil tanks ran over during normal well production activity because oil wasn't hauled.  Dispatched oil haulers to haul oil. Recovered oil from lined containment with vacuum truck and wash containment.		
Describe Area Affected and Cleanup Action Taken.*  All fluid remained in secondary containment berm, 30/30Bbbs recovered.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Zack Laird		Approved by Environmental Specialist: 	
Title: Sr. EHS Manager		Approval Date: 2/17/15	Expiration Date: N/A
E-mail Address: ZLaird@rkixp.com		Conditions of Approval: Remediation per O.C.D. Rules & Guidelines <input type="checkbox"/> Attached <input type="checkbox"/>	
Date: 02/12/15 Phone: 405-987-2213		SUBMIT REMEDIATION PROPOSAL NO	

\* Attach Additional Sheets If Necessary

LATER THAN: 3/17/15

2RP-2814