## District I 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 NM OIL CONSERVATION
ARTESIA DISTRICT

Form C-141 Revised August 8, 2011

2RP-2833

FEB 2 3 2015 Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

**RECEIVED** 

Release Notification and Corrective Action													
nAB15	0553	<b>OPERA</b>	ГOR			al Report	$\boxtimes$	Final Repor					
Name of Co	mpany: C	Contact: Robert McNeill											
Address: 60 Facility Nar		Telephone No. 432-230-0077 Facility Type: Battery											
		r: Federal API No. 30-015-37949											
Surface Ow	ner: reder												
TT 1: T	Unit Letter   Section   Township   Range   Feet from the   North/South Line   Feet from the   East/West Line   County												
P Unit Letter						h/South Line South	Feet from the 560'	1			Coun Edd	-5	
	Latitude32.1105744484693 Longitude -103.965525193251												
	NATURE OF RELEASE												
Type of Release:							Volume of Release: Volume Recovered:						
Produced Wa Source of Rel						19 bbls PW							
Tanks	iease:					Date and Hour of Discovery: /29/2015 4:30 pm							
Was Immediate Notice Given?  ☐ Yes ☐ No ☒ Not Required							If YES, To Whom?						
D 1111 0		<u></u>	Yes	No 🖾 Not Red	<del></del>			<del></del> _					
By Whom? Was a Watero	course Reac	Date and Hour:  If YES, Volume Impacting the Watercourse.											
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,													
If a Watercou	rse was Imp	oacted, Descri	be Fully.*			<u> </u>							
											•		
Describe Cause of Problem and Remedial Action Taken.*													
This release was caused by a failed check valve. The result of the failure caused the water tanks to over flow. Vacuum trucks were dispatched to recover													
, state of the sta	standing fluid.												
Describe Area	Affected a	nd Cleanup A	ction Take						<del></del>				
		•			-								
This release o	This release occurred within a lined facility. All fluids were able to be recovered and disposed of at an NMOCD approved facility.												
<u> </u>	I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and												
I hereby certif	y that the in operators a	formation giv	en above report and	is true and complet I/or file certain rele	te to t	he best of my l	cnowledge and un	derstan	d that pursu	uant to NMC	OCD ru	les and	
public health of	or the enviro	onment. The	acceptance	of a C-141 report	by th	e NMOCD ma	rked as "Final Re	port" d	oes not relie	eve the opera	ator of	liability	
should their of	perations ha	ve failed to a	dequately i	nvestigate and remance of a C-141 re	nediat	e contaminatio	n that pose a threa	at to gre	ound water,	surface wat	er, hun	nan health	
federal, state,					port u		the operator of re	sponsi		пірпансе мі	itii aiiy	otilei	
Signature:							OIL CONSERVATION DIVISION						
Title: Senior Environmental Coordinator Ap							Approval Date: 2 24   5   Expiration Date: N/A						
E-mail Address: atrujillo@concho.com							Conditions of Approval: FINAL Attached						
Date: Februa	ry 23, 2015		F11	141	_	-		1					
* Attach Additi			75-748-69 rv							1 - 0			