State of New Mexico **Energy Minerals and Natural Resources** 

> Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

## NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141 Revised August 8, 2011

MAR 0 3 2015 Submit I Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

API No. 30-015-33861

## **Release Notification and Corrective Action**

	OPERATOR	Initial Report	🛛 Final Report
Name of Company: BOPCO, L.P.	Contact: Tony Savoie		
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329		
Facility Name: Poker Lake Unit #216	Facility Type: Exploration and I	Production	
			· · · · · · · · · · · · · · · · · · ·

## LOCATION OF RELEASE

Mineral Owner: Federal

Unit Letter M	Section 17	Township 24S	Range 30E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy

Latitude N 32.21200 Longitude W 103.91197

## NATURE OF RELEASE Values of Dalagas, 25 bble of

Type of Release: Produced water and crude oil	Volume of Release: 25 bbls of PW and 25 bbls crude oil	Volume Recovered: 40 bbls total fluid					
Source of Release: Flow line	Date and Hour of Occurrence: 3/21/10 Approximately 8:00 p.m.	Date and Hour of Discovery: 3/21/10 at 8:30 p.m.					
Was Immediate Notice Given?	If YES, To Whom?						
🛛 Yes 🗌 No 🗌 Not Required	NMOCD Emergency #104 "Randy"						
By Whom? Tony Savoie	Date and Hour: 3/22/10 at 12:06 p.m						
Was a Watercourse Reached?	If YES, Volume Impacting the Watercourse.						
Yes 🛛 No							
If a Watercourse was Impacted, Describe Fully.*							
Describe Cause of Problem and Remedial Action Taken.* A 2 3/8" flow developed a leak under the caliche road known a Rawhide road, the flow line is a conduit under the road with approximately 20 other flow lines. Crews started shutting in wells and excavating the area to determine the exact well. A vacuum truck was on-site and began recovering oil from the excavated area. The affected line was replaced the same day.							
Describe Area Affected and Cleanup Action Taken.* The spill affected approximately 1000 sq.ft. of lease road and approximately 1800 sq. ft. of pasture land. The area in the road was excavated to repair the line, due to the number of lines in the conduit and traffic requirements soil samples were collected from the excavated area in the road and backflilled. The area will be delineated and a remediation plan will be submitted in accordance with the NMOCD recommended guidelines. Basin Environmental Services began the field activities on 11/10/14 and completed the excavation, disposal and replacement of approximately 340 cubic yards of soil on 1/5/15. Please reference the Soil Closure Request dated January 2015.							
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.							
	OIL CONSERV.	ATION DIVISION					
Signature: Ou Surve							
	Approved by Environmental Specialist:						
Title: Waste Management and Remediation Specialist	Approval Date: 3/4/15 E	Expiration Date: NIA					
E-mail Address: tasavoie@basspet.com	Conditions of Approval:	Attached					
Date: 3/3/2015 Phone: 432-556-8730	tin	ul					

\* Attach Additional Sheets If Necessary

2RP-0547