NM OIL CONSERVATION

District I 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 1220 S. St. Francis Dr., Santa Fe. NM 87505

State of New Mexico Energy Minerals and Natural Resources AR 0 3 2015

ARTESIA DISTRICT

Form C-141 Revised August 8, 2011

Oil Conservation Division

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

1220 South St. Francis Dr. Santa Fe. NM 87505

RECEIVED

Release Notification and Corrective Action OPERATOR Initial Report. Name of Company Devon Energy Production Contact Daniel Suniga- Devon Production Foreman Address 6488 Seven Rivers Hwy Artesia, NM 88220 Telephone No. 575-390-5850 Facility Type Oil Facility Name Aldabra 25 Fed 6H Surface Owner Federal Mineral Owner Federal API No. 30-015-38602 LOCATION OF RELEASE Unit Letter Township Feet from the North/South Line Feet from the East/West Line Section Range County SOUTH 25 238 31E 200 EDDY P 1050 EAST Latitude: 32.2686792382846 Longitude: -103.726368372316 **NATURE OF RELEASE** Type of Release Spill Oil Volume of Release 20 bbls oil Volume Recovered 20 bbls oil Source of Release Tank Overspill Date and Hour of Occurrence Date and Hour of Discovery November 23, 2014 3:00 AM November 23, 2014 3:00 AM Was Immediate Notice Given? If YES, To Whom? ☑ Yes ☐ No ☐ Not Required Mike Bratcher- OCD Jeff Robertson-BLM By Whom? Kevin Phillips- Devon Assistant Production Foreman Date and Hour November 23, 2014 1:15 PM Was a Watercourse Reached? If YES, Volume Impacting the Watercourse ☐ Yes ☒ No If a Watercourse was Impacted, Describe Fully.* N/A Describe Cause of Problem and Remedial Action Taken.* Temporary tank ran over and spilled 20 bbls of oil into lined containment. Tanks were switched to prevent continued overflow. Describe Area Affected and Cleanup Action Taken.* 20 bbls of oil were spilled over into a 40'x100' lined containment. All 20 bbls were recovered via vacuum truck provided by Contract Trucking Company on November 23, 2014. Then liner was then examined and found to be intact. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. OIL CONSERVATION DIVISION Signature: Churi Fornández Approved by Environmental Specialist: Printed Name: Yuri Fernandez Title: Field Admin Support Approval Date: **Expiration Date:** E-mail Address: Yuri.Fernandez@dvn.com Conditions of Approval: FINAL Attached

Attach Additional Sheets If Necessary

Date: December 16, 2014

Phone: 575.748.1846

2RD-2865