

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

**NM OIL CONSERVATION**  
ARTESIA DISTRICT

APR 30 2015

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.  
**RECEIVED**

**Release Notification and Corrective Action**

**NAB1512439250**

**303900 OPERATOR**

☐ Initial Report ☐ Final Report

Name of Company	Memorial Production Operating LLC	Contact	Heather Dolphin
Address	500 Dallas Street Houston TX 77002	Telephone No.	832-797-1334
Facility Name	North Square Lake Unit # 154	Facility Type	Well

Surface Owner	Mineral Owner	API No.	30-015-04986
---------------	---------------	---------	--------------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
F	34	16S	31E					Eddy

Latitude 32°52'46"N Longitude -103° 51' 38"W

**NATURE OF RELEASE**



Type of Release	Oil	Volume of Release	7bbbls	Volume Recovered	2bbbls
Source of Release	2" Steel Flow Line	Date and Hour of Occurrence	4/29/15	Date and Hour of Discovery	11:35
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	BLM		
By Whom?	Heather Dolphin	Date and Hour	4/30/15		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	n/a		

If a Watercourse was Impacted, Describe Fully.\*  
n/a

Describe Cause of Problem and Remedial Action Taken.\*  
The 2" steel flow line going from the NSLU #145 to the battery developed a pin hole approximately 60 yards off location and out in the field. It spilled approx. 7bbbls of oil.

Describe Area Affected and Cleanup Action Taken.\*  
2bbbls were recovered by vac. Truck. A clamp was put on the pipe to cover the hole. Will follow the BLM procedure of scrapping up contaminated ground.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Heather Dolphin	Approved by Environmental Specialist: 	
Title: Sr. Regulatory Specialist	Approval Date: 5/4/15	Expiration Date: N/A
E-mail Address: heather.dolphin@memorialrd.com	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines <input type="checkbox"/>	
Date: 4/30/15 Phone: 832-797-1334	<b>SUBMIT REMEDIATION PROPOSAL NO</b>	

\* Attach Additional Sheets If Necessary

LATER THAN: 6/4/15

2RP. 2982