

NM OIL CONSERVATION
ARTESIA DISTRICT

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

APR 29 2015

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1512056213

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: OXY USA INC	Contact: Chris Jones
Address: 102 S. Main St. Carlsbad, NM 88220	Telephone No.: 575-628-4121
Facility Name: State 2 #3 CTB	Facility Type: Battery

Surface Owner: State	Mineral Owner:	API No.: 30-015-26877
-----------------------------	----------------	------------------------------

LOCATION OF RELEASE

Unit Letter I	Section 2	Township 22S	Range 31E	Feet from the 2310'	North/South Line South	Feet from the 330'	East/West Line East	County Eddy
-------------------------	---------------------	------------------------	---------------------	-------------------------------	----------------------------------	------------------------------	-------------------------------	-----------------------

Latitude **32.41591 N** Longitude **-103.74235 W**


NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 90 bbls	Volume Recovered: 85 bbls
Source of Release: 2" Dump Line Corroded	Date and Hour of Occurrence 3/30/2015	Date and Hour of Discovery 3/30/2015
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour: 4/19/15 8:15 AM (Per e-mail)	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		

Describe Cause of Problem and Remedial Action Taken: **A 2" dump line corroded causing a 90 barrel release within the containment of the facility. A vac truck was immediately call to the location and recovered 85 barrel of fluids.**

Describe Area Affected and Cleanup Action Taken.* ☐ The impacted area was inside the containment of the facility. Talon/LPE has already performed site assessment and soil sampling activities. A work plan will be drafted by May 1, 2015.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Chris Jones <small>Digitally signed by Chris Jones DN: cn=Chris Jones, o, ou, email=ckjones888@yahoo.co m, c=US Date: 2015.04.28 15:46:59 +05'00'</small>	OIL CONSERVATION DIVISION	
	Approved by Environmental Specialist: 	
Printed Name: Chris Jones	Approval Date: 4/30/15	Expiration Date: N/A
Title: HES Specialist	Conditions of Approval:	
E-mail Address: Christopher.Jones@oxy.com	Attached <input type="checkbox"/>	
Date: 4/28/2015 Phone: 575-628-4121	Remediation per O.C.D. Rules & Guidelines SUBMIT REMEDIATION PROPOSAL NO LATER THAN: 5/30/15	

* Attach Additional Sheets If Necessary

2RP-2975