

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141

Revised August 8, 2011

APR 29 2015

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1512436764

OPERATOR

Initial Report Final Report

Name of Company: BOPCO, L.P. <i>2100737</i>	Contact: Bradley Blevins
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: PLU PC 3 Water Line; release is located 150' south of PLU-CVX-JV-BS 16H	Facility Type: Exploration and Production

Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-40581
------------------------	------------------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	3	25S	30E					Eddy

Latitude: N 32.152221° Longitude: W 103.867119°

NATURE OF RELEASE

Type of Release: produced water	Volume of Release: 34 bbls	Volume Recovered: 5 bbls
Source of Release: Line developed a small hole releasing fluid to ground surface	Date and Hour of Occurrence: 4/21/15 @ 9:46 am	Date and Hour of Discovery: 4/21/15 @ 9:46 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher, OCD; Jim Amos, BLM via email	
By Whom? Bradley Blevins	Date and Hour: 4/21/15 @ 2:59 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse: Not Applicable	

If a Watercourse was Impacted, Describe Fully.* Not Applicable

Describe Cause of Problem and Remedial Action Taken.*
Line developed a small hole releasing fluid to ground surface, the fluid ran to the SW along ROW.

Describe Area Affected and Cleanup Action Taken.*
The release impacted approximately 3,000 sq. ft. of ROW. Vacuum truck recovered 5 bbls of fluid. The area will be remediated in accordance with the NMOCD and BLM remediation guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Bradley Blevins</i>	OIL CONSERVATION DIVISION	
Printed Name: Bradley Blevins	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Assistant Remediation Foreman	Approval Date: 5/4/15	Expiration Date: N/A
E-mail Address: bblevins@basspet.com	Conditions of Approval:	
Date: 4-29-15	Remediation per O.C.D. Rules & Guidelines	
Phone: 432-214-3704	Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

SUBMIT REMEDIATION PROPOSAL NO
LATER THAN: 10/4/15

2RP-2980