

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report



Name of Company	COG Operating LLC	Contact	Pat Ellis
Address	550 W. Texas, Suite 1300 Midland, Texas 79701	Telephone No.	(432) 230-0077
Facility Name	Burch Keely Unit #632	Facility Type	Tank Battery
Surface Owner: Federal	Mineral Owner	Lease No. (API#)	30-015-40327

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	24	17S	29E					Eddy

Latitude N 32.81425° Longitude W 104.03443°

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release 134 bbls	Volume Recovered 130 bbls
Source of Release: BKU #112 Injection Line	Date and Hour of Occurrence 08/14/2012	Date and Hour of Discovery 08/14/2012 12:30 p.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher-OCD Jim Amos-BLM Terry Gregston-BLM	
By Whom? Josh Russo	Date and Hour 08/15/2012 8:50 a.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* While preparing a new well pad a dozer accidentally hit a buried injection line from the BKU #112 causing the release of fluid onto the site. The line has been repaired and returned to service.		
Describe Area Affected and Cleanup Action Taken.* COG conducted an emergency cleanup of the spill. Soil exceeding the RRAL for TPH and BTEX were removed and transported to proper disposal. Once excavated, Tetra Tech collected confirmation samples from the open excavation. Based on the results, the excavation was backfilled with clean soil and then brought up to surface grade. Tetra Tech prepared a closure report and submitted it to NMOCD for review.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Ike Tavarez	Approved by District Supervisor: 	
Title: Project Manager	Approval Date: 8/22/15	Expiration Date:
E-mail Address: Ike.Tavarez@TetraTech.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 10-25-12	Phone: (432) 682-4559	

* Attach Additional Sheets If Necessary

2AP 1270
Final