District 1 1625 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Avenue, Artesia. NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141 Revised October 10, 2003

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

| | OPERATOR | ☐ Initial Report |
|--|--|----------------------------|
| Name of Company COG Operating LLC | Contact Pat Ellis | |
| Address 550 W. Texas, Suite 1300 Midland, Texas 79701 | Telephone No. (432) 230-0077 | |
| Facility Name Tenneco State #1 | Facility Type Tank Battery | |
| Surface Owner State Mineral Owner | · | Lease No. 30-015-29809 |
| LOCATION OF RELEASE | | |
| | | /West Line County |
| M 20 17-S 29-E | | Eddy |
| Latitude N 32.81351° Longitude W 104.10428° | | |
| NATURE OF RELEASE | | |
| Type of Release: Produced Water | Volume of Release | Volume Recovered |
| Source of Release | Date and Hour of Occurrence | Date and Hour of Discovery |
| Water Tank | 1/17/2012 | 1/17/2012 10:00 p.m. |
| Was Immediate Notice Given? | If YES, To Whom? | |
| ☐ Yes ☒ No ☒ Not Required | | |
| By Whom? Was a Watercourse Reached? | Date and Hour If YES, Volume Impacting the Watercourse. | |
| Was a Watercourse Reactied: ☐ Yes ☑ No | N/A | |
| If a Watercourse was Impacted, Describe Fully.* | | |
| | | |
| N/A | | |
| Describe Cause of Problem and Remedial Action Taken.* | | |
| The water pump wasn't working and in return the water tank tan over. The water pump had an electrical failure that has been repaired and it has been returned to service. | | |
| Describe Area Affected and Cleanup Action Taken.* | | |
| Tetra Tech inspected and collected samples to define spills extent. The TPH and BTEX were below the RRAL and the chloride concentrations did not show a significant impact to the soils. Based on the results, no remedial action was performed at the site. Tetra Tech prepared closure report and submitted to NMOCD for review. | | |
| I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. | | |
| 1124 | OIL CONSERV | ATION DIVISION/ |
| Signature: | | |
| | Approved by District Supervisor: | |
| Printed Name: Ike Tavarez (agent for COG) | | |
| Title: Project Manager | Approval Date: 4/12/15 1 | Expiration Date: |
| E-mail Address: ike.tavarez@tetratech.com | Conditions of Approval: | August 🖂 |
| Date: 7-26-17 Phone: (432) 682-4559 | | Attached |
| Attach Additional Sheets If Necessary | | |
| ···· | | 2RP- 1014 |
| · | | 2RP-1014 Final |
| | • | , |