

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company OXY USA	Contact Kelton Beaird	
Address 1502 W. Commerce Carlsbad, NM 88220	Telephone No. (O) 575-628-4100	
Facility Name US 13 federal 1Y	Facility Type Well with gathering lines	
Surface Owner BLM	Mineral Owner BLM	Lease No. 30-015-24193

LOCATION OF RELEASE

Unit Letter	Section 13	Township 22S	Range 24E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
-------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	----------------

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 100bbls.	Volume Recovered 0
Source of Release Flowline from the US 13 fed. 2	Date and Hour of Occurrence	Date and Hour of Discovery 10-28-09 @ 3:00pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher-NMOCD (left message)	
By Whom? Kelton Beaird-HES (Oxy)	Date and Hour See above	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

The flowline from the US 13 fed 2 ruptured next to the 13-1Y location. All water soaked in before a vac-truck could be called

Describe Area Affected and Cleanup Action Taken.*

From the Point of Release, water traveled approx 300 feet by 20 feet, then split. One split ran approx. 84 feet by 5 feet wide. The other split ran approx 400 feet by 20 feet wide. The area was sampled, a clean-up plan was approved by Mike Bratcher with the NMOCD to excavate 6" at TP1. Clean native soil was used for backfill and area was re-seeded.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Kelton Beaird	Approved by District Supervisor: 	
Title: HES Specialist	Approval Date: 7/24/15	Expiration Date: NA
E-mail Address: kelton_beaird@oxy.com	Conditions of Approval: Final	Attached <input type="checkbox"/>
Date: 7-14-10		

* Attach Additional Sheets If Necessary

2RP-667