

NM OIL CONSERVATION

ARTESIA DISTRICT

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

MAY 13 2015

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
RECEIVED accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1513456141

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company: COG Operating LLC 217955	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077
Facility Name: Copperhead 31 Federal #1H	Facility Type: Battery



Surface Owner: Federal	Mineral Owner:	API No. 30-015-38532
------------------------	----------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
H	31	26S	29E	480'	South	480'	East	Eddy

Latitude 32.0014319408279 Longitude -104.01685318585

NATURE OF RELEASE

Type of Release: Oil & Produced Water	Volume of Release: 10 bbls Oil & 100 bbls PW	Volume Recovered: 9 bbls Oil & 98 bbls PW
Source of Release: Tank Overflow	Date and Hour of Occurrence: 4/19/2015 3:30 pm	Date and Hour of Discovery: 4/19/2015 3:30 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher - NMOCD / Jim Amos - BLM	
By Whom? Amanda Trujillo	Date and Hour: 4/21/2015 6:10 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* The release was caused by water transfer pump failure which caused the tanks to overflow. Vacuum trucks were dispatched to recover all standing fluid.		
Describe Area Affected and Cleanup Action Taken.* This release occurred within a lined facility. All fluid was recovered the facility put back into service.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Amanda Trujillo	Approved by Environmental Specialist: 	
Title: Senior Environmental Coordinator	Approval Date: 5/14/15	Expiration Date: N/A
E-mail Address: atrujillo@concho.com	Conditions of Approval: Final	Attached <input type="checkbox"/>
Date: May 13, 2015 Phone: 575-748-6940		

* Attach Additional Sheets If Necessary

2RP 3003