


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	COG Operating LLC	Contact	Pat Ellis
Address	600 West Illinois Avenue, Midland, TX 79701	Telephone No.	(432) 230-0077
Facility Name	SRO 102 SWD	Facility Type	SWD

Surface Owner: State	Mineral Owner	Lease No. (API#) 30-015-21398
----------------------	---------------	-------------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	16	26S	28E					Eddy

Latitude N 32.04381° Longitude W 104.09047°

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release 75 bbls	Volume Recovered 0 bbls
Source of Release: 4" Discharge Line	Date and Hour of Occurrence 10/21/2012	Date and Hour of Discovery 10/21/2012
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher-OCD	
By Whom? Michelle Mullins	Date and Hour 10/23/2012 11:17 a.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Our 4" produced water discharge line corroded and released fluid onto the SRO 102 SWD location. The discharge line has been repaired and returned to service.

Describe Area Affected and Cleanup Action Taken.*

Tetra Tech inspected and collected samples to define the spill extents. None of the soil samples exceeded the RRAL for TPH and BTEX. Elevated chloride were excavated and transported to proper disposal. The excavations were backfilled with clean soil and brought up to surface grade. Tetra Tech prepared a closure report for the NMOCD to review.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		OIL CONSERVATION DIVISION	
Printed Name: Ike Tavarez (agent for COG)		Approved by District Supervisor:	
Title: Project Manager		Approval Date: 7/7/15	Expiration Date: N/A
E-mail Address: Ike.Tavarez@TetraTech.com		Conditions of Approval:	Attached <input type="checkbox"/>
Date: 3-14-13	Phone: (432) 682-4559		

Attach Additional Sheets If Necessary

2RP-1388