

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1522256800 OPERATOR ☒ Initial Report ☐ Final Report  
Name of Company: Mewbourne Oil Company 14744 Contact: Zack Thomas  
Address: PO Box 5270 Hobbs NM 88241 Telephone No. 575-393-5905  
Facility Name: Santo Nino 29 Fed SWD #1 #5 \* Facility Type: Producing Oil Well

Surface Owner: BLM Mineral Owner: BLM API No. 30-015-28689

\*SWD is marked as #5

LOCATION OF RELEASE

30-D15 28698

Unit Letter G	Section 29	Township 18S	Range 30E	Feet from the 1932'	North/South Line North	Feet from the 1923'	East/West Line East	County Eddy
------------------	---------------	-----------------	--------------	------------------------	---------------------------	------------------------	------------------------	----------------

Latitude 32.720294 Longitude -103.992032

NATURE OF RELEASE

Type of Release: Produced water	Volume of Release: 1170 bbls	Volume Recovered: 1170 bbls
Source of Release: Water Tank	Date and Hour of Occurrence 6-13-15 6:30 pm	Date and Hour of Discovery 6-13-15 7:00 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jim Amos (BLM)	
By Whom? Robin Terrell	Date and Hour 6-14-15 11:30 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

NM OIL CONSERVATION  
ARTESIA DISTRICT

If a Watercourse was Impacted, Describe Fully.\*

AUG 10 2015

Describe Cause of Problem and Remedial Action Taken.\*

RECEIVED

Cause of leak: The tank battery was struck by lightning. Upon being struck, the battery caught fire and burned a hole in the corner of the containment. Fire department was immediately contacted and vacuum trucks arrived to clean the spill as soon as the location was deemed safe.

Describe Area Affected and Cleanup Action Taken.\*

Affected area: The produced water leaked out of the SW corner of the containment behind location. Vacuum trucks recovered all of the standing water and any visually contaminated soil was taken to an approved NMOCD disposal site. Final remediation will be conducted in accordance with the NMOCD's Guidelines for Remediation of Spills, Leaks and Releases.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: Z. Thomas

Printed Name: Zack Thomas

Approved by Environmental Specialist: [Signature]

Title: Environmental Rep.

Approval Date: 8/10/15

Expiration Date: NA

E-mail Address: zthomas@mewbourne.com

Conditions of Approval:

Attached ☐

Date: 6-18-15

Phone: 575-602-2188

Remediation per O.C.D. Rules & Guidelines

SUBMIT REMEDIATION PROPOSAL NO  
LATER THAN: 9/11/15

\* Attach Additional Sheets If Necessary

2RP-3194