

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

30-015-04600
n MCB 0602330783
Release Notification and Corrective Action

OPERATOR

x Initial Report ☐ Final Report

Name of Company Tom R. cone	Contact Rick L Houston
Address 1304 W. Broadway Place Hobbs N.M. 88240	Telephone No. 505 390 9611
Facility Name Southern California pet corp. 14-1	Facility Type oil well

Surface Owner Federal Land	Mineral Owner Tom R. Cone	Lease No. NM-01085
----------------------------	---------------------------	--------------------

LOCATION OF RELEASE

Unit Letter H	Section 14	Township 19s	Range 30e	Feet from the 2310	North Line	Feet from the 330	East Line	County EDDY
------------------	---------------	-----------------	--------------	-----------------------	------------	----------------------	-----------	-------------

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release oil	Volume of Release 5 bbl	Volume Recovered 3
Source of Release Production Storage Tank	Date and Hour of Occurrence 12-26-05	Date and Hour of Discovery 12-27-05
Was Immediate Notice Given? x Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Terry BLM Carlsbad NM	
By Whom?	Date and Hour	
Was a Watercourse Reached? Yes x No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

RECEIVED

JAN 09 2006

OCU-ANTECO



Describe Cause of Problem and Remedial Action Taken.*

Hole came in back of production tank. Tank was repairs. Oil was sold.

Describe Area Affected and Cleanup Action Taken.*

Behind production tank down the hill to a raven for about 50 yards. Oil was suck back up. Dirt down the hill was removed. Raven was wipe down microbes were sprayed on oil stain in raven. We will stay in contact with Terry of the BLM in Carlsbad NM.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: RICK L Houston	Approved by District Supervisor: TIM GUM by MB 	
Title: Field Superintendent	Approval Date: 1/23/06	Expiration Date: N/A
E-mail Address: RHOU121198@valornet.com	Conditions of Approval: per form BLM / OGD Approved remediation	Attached <input type="checkbox"/>
Date: 1-2-06	Phone: 505-390-9611	

* Attach Additional Sheets If Necessary