

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141
Revised August 8, 2011

OCT 07 2015

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1528047930

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Apache Corporation	Contact	Bruce Baker
Address	2350 W Marland Street, Hobbs, NM 88240	Telephone No.	(432) 631-6982
Facility Name	Apache State SWD # 3	Facility Type	SWD

Surface Owner	State	Mineral Owner		API No.	30-015-38978
---------------	-------	---------------	--	---------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
L	19	17S	31E					Eddy

Latitude 32.816536 Longitude -103.916730

NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	7 barrels of produce water	Volume Recovered	0 bbls
Source of Release	flow line	Date and Hour of Occurrence	10/2/2015	Date and Hour of Discovery	10/2/2015
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?		Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

A 3 inch metal transition developed a hole resulting in the release. The flow line was isolated and repaired.

Describe Area Affected and Cleanup Action Taken.*

The release affected total of 695 square feet with 100 square feet of pasture and 595 square feet on lease road and NM state pit 337. The area was mapped and initial field sampling was conducted. The state land office was notified due to contamination in pit 337.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Bruce Baker</i>		OIL CONSERVATION DIVISION	
Printed Name: Bruce Baker		Signed By: <i>[Signature]</i> Approved by Environmental Specialist:	
Title: Environmental Technician		Approval Date: 10/7/15	Expiration Date: N/A
E-mail Address: larry.baker@apachecorp.com		Conditions of Approval:	
Date: 10/7/2015 Phone: (432) 631-6982		Attached <input type="checkbox"/>	
Remediation per O.C.D. Rules & Guidelines			

* Attach Additional Sheets If Necessary

SUBMIT REMEDIATION PROPOSAL NO
LATER THAN: 11/8/15

22P-3317