

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

### Release Notification and Corrective Action

**NAB1529955581** **OPERATOR** ☒ Initial Report ☐ Final Report

Name of Company: COG Operating LLC <b>217965</b>	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077
Facility Name: Copperhead 31 Federal Com #2H	Facility Type: Well

Surface Owner: Federal	Mineral Owner:	API No. 30-015-39791
------------------------	----------------	----------------------

### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	31	26S	29E	480	South	2140	East	Eddy

Latitude 32.0014229 Longitude -104.0222015

### NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 40 bbls PW	Volume Recovered: 10 bbls PW
Source of Release: Flowline	Date and Hour of Occurrence: 9/26/2015 5:00 pm	Date and Hour of Discovery: 9/26/2015 5:00 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher - NMOCD / Jim Amos - BLM	
By Whom? Lupe Carrasco	Date and Hour: Sunday, September 27, 2015 9:30 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*  
This release was caused by a poly flowline leak. A vacuum truck was dispatched to recover all standing fluid.

Describe Area Affected and Cleanup Action Taken.\*  
This release impacted the nearby pasture approximately 80' x 80'. Concho will have the spill site sampled to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>[Signature]</i>	OIL CONSERVATION DIVISION	
Printed Name: Amanda Trujillo	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Senior Environmental Coordinator	Approval Date: 10/26/15	Expiration Date: N/A
E-mail Address: atrujillo@concho.com	Conditions of Approval: <input type="checkbox"/> Attached <input type="checkbox"/>	
Date: October 10, 2015 Phone: 575-748-6940	Remediation per O.C.D. Rules & Guidelines SUBMIT REMEDIATION PROPOSAL NO LATER THAN: 11/26/15	

\* Attach Additional Sheets If Necessary

**NM OIL CONSERVATION**  
ARTESIA DISTRICT  
OCT 26 2015  
*late submission*  
**RECEIVED**

2RP-3354