

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

**NM OIL CONSERVATION**

ARTESIA DISTRICT

Form C-141  
Revised August 8, 2011

**JAN 06 2015**  
Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report  Final Report

Name of Company: BOPCO, L.P.	Contact: Tony Savoie
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: Hudson Federal Battery #1 On-Pad with Hudson Federal well #7 (2RP-1732)	Facility Type: Exploration and Production
Surface Owner: Federal	Mineral Owner: Federal
API No. 30-015-31513	

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
F	I	23S	30E					Eddy

Latitude N 32.336050 Longitude W 103.836788

**NATURE OF RELEASE**

Type of Release: Produced water	Volume of Release: 15 bbls	Volume Recovered: 8 bbls
Source of Release: Water transfer pump	Date and Hour of Occurrence: 5/17/13 time unknown	Date and Hour of Discovery: 5/17/13 9:00 a.m.
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*  
A 1/4" plug vibrated out of a water transfer pump causing water to spill inside of the 0 perm containment and sprayed outside on the ground. The plug was replaced.

Describe Area Affected and Cleanup Action Taken.\*  
Approximately 1800 sq. ft of tank battery pad and approximately 400 sq. ft. of pasture. The free standing fluid was recovered. The spill area will be remediated according to the NMOCD and BLM remediation guidelines.

*The spill was remediated in conjunction with a pit remediation and re-cap for the Hudson Federal #1 well, and the Hudson Federal #7 pumping well. A C-144 was submitted and approved for a trench burial for some of the pit material; a separate C-105 was filed for the pit closure. Please reference the Closure Request dated December 2014.*

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Tony Savoie	Approved by Environmental Specialist: 	
Title: Waste Management and Remediation Specialist	Approval Date: 11/4/15	Expiration Date: N/A
E-mail Address: tasavoie@basspet.com	Conditions of Approval: 	Attached <input type="checkbox"/>
Date: 1/6/15	Phone: 432-556-8730	

\* Attach Additional Sheets If Necessary

2RP-1732