

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141

Revised August 8, 2011

DEC 03 2015

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1533831844

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Devon Energy Production	Contact	Garry Michael, Production Foreman
Address	6488 Seven Rivers Hwy Artesia, NM 88220	Telephone No.	575-513-4895
Facility Name	Cotton Draw Unit 65	Facility Type	Salt Water Disposal

Surface Owner	Federal	Mineral Owner	State	API No.	30-015-10843
---------------	---------	---------------	-------	---------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	2	25S	31E	1980	North	1980	East	Eddy

Latitude: 32.161085918

Longitude: -103.746039442

NATURE OF RELEASE

Type of Release	Produced Water & Oil	Volume of Release	1202bbls	Volume Recovered	1197bbls
Source of Release	Storage Tanks	Date and Hour of Occurrence	November 27, 2015 12:00 PM	Date and Hour of Discovery	November 27, 2015 12:00 PM
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Jim Amos, BLM Mike Bratcher, OCD		
By Whom?	Garry Michael, Production Foreman	Date and Hour	Jim Amos, BLM November 27, 2015 3:00 PM Mike Bratcher, OCD November 27, 2015 3:05 PM		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse	N/A		

If a Watercourse was Impacted, Describe Fully.*

N/A

Describe Cause of Problem and Remedial Action Taken.*

Transfer pump went down causing the storage tanks to overflow releasing approximately 1202bbls produced water and oil into lined containment and on to location. The transfer pumps were immediately reset to start transferring water to stop the over flow.

Describe Area Affected and Cleanup Action Taken.*

The affected area on location was caused from an overflow of approximately 22bbls from lined containment starting Northeast and running Southwest on location causing a 70'x80' area on location next to the containment. The storage tanks overflowed releasing approximately 1196bbls produced water and approximately 6bbls oil with no fluids leaving location. A vacuum truck was called and recovered approximately 1179bbls produced water and approximately 1bbl oil from lined containment and approximately 12bbls produced water and approximately 5bbls oil from location. Lined containment was checked for holes and none were found. An environmental agency will be contacted for remediation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Federal, State, or Local Laws and/or Regulations:		<u>OIL CONSERVATION DIVISION</u>	
Signature: <i>Sheila Fisher</i>		Signed By <i>Mike Bratcher</i>	
Printed Name: Sheila Fisher		Approved by Environmental Specialist:	
Title: Field Admin Support		Approval Date: <i>12/4/15</i>	Expiration Date: <i>N/A</i>
E-mail Address: Sheila.Fisher@dvn.com		Conditions of Approval: Remediation per O.C.D. Rules & Guidelines Attached <input type="checkbox"/>	
Date: <i>12/3/15</i>	Phone: 575.748.1829	SUBMIT REMEDIATION PROPOSAL NO	

* Attach Additional Sheets If Necessary

LATER THAN: 11/11/16

2RP.3429