

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141

JAN 05 2016

Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1601137117

OPERATOR		<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Name of Company Devon Energy Production Company <i>4137</i>		Contact Rudy Zuniga Production Foreman	
Address 6488 Seven Rivers Hwy Artesia, NM 88210		Telephone No. 575-390-5435	
Facility Name Onyx PWU 29 #3		Facility Type Oil	
Surface Owner State		Mineral Owner State	API No 30-015-39373

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
L	29	19S	29E	2145	South	330	West	Eddy

Latitude: N 32°63'04.88"

Longitude: W 104°10'45.09"

NATURE OF RELEASE

Type of Release Spill Oil	Volume of Release 5 bbls	Volume Recovered 0 bbls
Source of Release Lact Unit	Date and Hour of Occurrence 1.4.16 @ 8:40 am	Date and Hour of Discovery 1.4.16 @ 8:40 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? OCD @ Heather Patterson	
By Whom? Jesse Armendariz Assistant Production Foreman	Date and Hour 1.5.2016 @ 1:55 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* Leak on the Lact Unit caused a 5 bbl oil spill. Well was shut in to prevent further release. Still investigating where the leak started due to the snow.		
Describe Area Affected and Cleanup Action Taken.* 5 bbls oil was released on the South, South West side of the facility. None of the spill was recovered due to weather. Size of affected area is 20' x 30'. All fluids remained on the location. Environmental agency will be contacted for remediation.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: <i>Corina Moya</i>	OIL CONSERVATION DIVISION	
Printed Name: Corina Moya	Signed By <i>[Signature]</i>	
Title: Field Admin Support	Approved by Environmental Specialist:	
E-mail Address: corina.moya@dmv.com	Approval Date: 1/11/16	Expiration Date: N/A
Date: 1.5.16 Phone: 575.746.5559	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines Attached <input type="checkbox"/> SUBMIT REMEDIATION PROPOSAL NO LATER THAN: <i>2/12/16</i>	

* Attach Additional Sheets If Necessary

2RP-3481