NM OIL CONSERVATION

ARTESIA DISTRICT

Submit One Copy To Appropriate District Office	State of New Mexico Energy, Minerals and Natural Resources		JAN 0 5 2016 Form C-103 Revised November 3, 2011
District I 1625 N, French Dr., Hobbs, NM 88240 District II			**************************************
811 S. First St., Artesia, NM 88210 District III	OIL CONSERVATION DIVISION 1220 South St. Francis Dr.		5. Indicate Type of Lease
1000 Río Brazos Rd., Aztec. NM 87410 District IV	Santa Fe, NM 87505		STATE FEE 6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505			
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			7. Lease Name or Unit Agreement Name LITTLE BOX STATE
PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other			8. Well Number 5
2. Name of Operator NADEL AND GUSSMAN PERMIAN, L.L.C.			9. OGRID Number 155615
3. Address of Operator 601 N. MARIENFELD, SUITE 508, MIDLAND, TX 79701			10. Pool name or Wildcat LITTLE BOX CANYON: MORROW
4. Well Location			
Unit Letter G: 1980' feet from the North line and 1980' feet from the East line Section 36 Township 208 Range 21E NMPM County Eddy			
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 4382' GR			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
_ ·			SEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORTEMPORARILY ABANDON CHANGE PLANS COMMENCE DR		_	
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB			
OTHER: Location is ready for OCD inspection after P&A			
 All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned. A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the 			
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR PERMANENTLY STAMPED ON THE MARKER'S SURFACE.			
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other production equipment.			
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.			
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed			
from lease and well location. All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have to be removed.)			
All other environmental concerns have been addressed as per OCD rules.			
Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-tetrieved flow lines and pipelines.			
If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well			
location, except for utility's distribution infrastructure. THERE IS AN 8" GAS GATHERING LINE ON THE SOUTH EDGE OF LOCATION THAT CAN'T BE REMOVED When all work has been completed, return this form to the appropriate District office to schedule an inspection.			
SIGNATURE: Sid Day TITLE: NM FIELD SUEPERINTENDENT DATE: 12-17-15			
TYPE OR PRINT NAME: BILL DOUGHERTY E-MAIL: SPRESLEY@NAGUSS.COM PHONE: (432) 682-4429 For State Use Only			
APPROVED BY: Jour Marales TITLE compliance Africer DATE 1/15/16			