

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION
ARTESIA DISTRICT
FEB 17, 2016
RECEIVED
Form C-141
Revised August 8, 2011
Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nAB1604933977
OPERATOR ☒ Initial Report ☐ Final Report
Name of Company Oxy Permian Ltd. 192463
Address 6 Desta Drive, Midland, TX 79705
Facility Name MOC SWD Well Battery
Facility Type Battery
Surface Owner BLM Mineral Owner API No. 30-015-21669

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
K	7	20S	25E					Eddy

Latitude N 32.58654° Longitude W 104.52686°

NATURE OF RELEASE

Type of Release Oil	Volume of Release 50 bbls	Volume Recovered 25 bbls
Source of Release Holes in bottom of tank	Date and Hour of Occurrence 02/04/2016	Date and Hour of Discovery
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bracher, Heather Patterson-NMOCD; Shelly Tucker-BLM	
By Whom? Kathy Purvis @ BBC International Inc.	Date and Hour 02/05/2016 @ 1:53 pm 1:59pm (e-mail)	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* Holes in the bottom of tank caused a leak of 50 bbls of oil. A vacuum truck recovered 25 bbls of oil and the holes were repaired.		
Describe Area Affected and Cleanup Action Taken.* The affected area is approximately 25' x 100' on location inside the containment. Remediation will be completed in accordance with an approved remediation plan from NMOCD and the BLM.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: [Signature]	OIL CONSERVATION DIVISION	
Printed Name: Casey Summers	Approved by Environmental Specialist: [Signature]	
Title: NM Environmental Advisor	Approval Date: 2/18/16	Expiration Date: N/A
E-mail Address: Casey_Summers@oxy.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 2-16-16 Phone: (575) 513-8289		

* Attach Additional Sheets If Necessary

2RP-3556