	Y						
		NMSOIL GONSERVATION Energy, Minerals and Natural Resources FEB 05 2016 OIL CONSERVATION DIVISION 1220 South St. Francis Dr. Santa Fe, NM 87505				n C-103	
	<u>District 1</u> Energy, Mineral's a				Revised November 3, 2011 WELL API NO.		
	District II ON CONCEDU						
	District III 1220 South				of Lease ☑ FEE [	<b>–</b>	
	1000 Rio Brazos Rd., Aztec, NM 87410 District IV Santa Fe,				FEE Lase No.	<u> </u>	
	1220 S. St. Francis Dr., Sonta Fe, NM 87505			LG3215			
	SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or Unit Agreement Name			
٦	OD NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPE DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM	MESA 20-1 STATE  8. Well Number					
	PROPOSALS.)  1. Type of Well: ⊠Oil Well □ Gas Well □ Other	8. Well Number					
	2. Name of Operator			9. OGRID Number			
	OXY USA INC	16696					
	3. Address of Operator PO BOX 4294; HOUSTON, TX 77210			10. Pool name or Wildcat ARTESIA QUGBSA			
	4. Well Location			11112011 2001			
	Unit Letter N: 990 feet from the SOUTH line and 1650 feet from the WEST line						
Section 20 Township 18S Range 28E NMPM County EDDY							
ı	11. Elevation (Show whe			45 a 7			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data							
-	NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK D PLUG AND ABANDON	SEQUENT REPORT OF: K □ ALTERING CASING □					
	MPORARILY ABANDON 🔲 CHANGE PLANS 🔲 COMMENCE DRILLING OPNS. 🗍 P AI						
PULL OR ALTER CASING				JOB 🗆			
	OTHER:					·	
	All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.						
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.  A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the							
<u>OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR</u>							
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.							
☐ The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow line							
other production equipment.  Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.							
							If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been remove
1	from lease and well location.						
	All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have to be removed.)						
1	All other environmental concerns have been addressed as per OCD rules.						
	Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-retrieved flow lines and pipelines.						
	If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well						
I	location, except for utility's distribution infrastructure.						
1	When all work has been completed, return this form to the appro	opriate D	istrict office to sche	dule an inspection.			
				_			
5	SIGNATURE TIME SMACK TI	TLE_ H	IES OPS COORDII	NATORDATE	1-19-16	_	
_	TYPE OR PRINT NAME _ FRANK BARNETT E-MAIL:	frank k	numant@ass cam	PHONE: 575 20	N7_2414		
	For State Use Only		wrnent@oxy.com		)&-6717\ \	_ (	
		1 7	,	( ) ]	1	١.	

OH Release

APPROVED BY:
Conditions of Approval (if any)