



District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

### Release Notification and Corrective Action

#### OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: Chevron	Contact: Bradley Blevins	
Address: 1616 West Bender	Telephone No.: (575) 391-1462 ext. 86424	
Facility Name: Baish Federal Tank Battery	Facility Type: Tank Battery	
Surface Owner: Federal	Mineral Owner: Federal	Lease No.: LC029389A

#### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	9	18S	31E					Eddy

Latitude: N 32° 46' 2.0" Longitude: W 103° 52' 18.4"

#### NATURE OF RELEASE

Type of Release: Produced water	Volume of Release: ~160 bbls	Volume Recovered: ~110 bbls
Source of Release: Tank Battery	Date and Hour of Occurrence: May 9, 2013 A.M.	Date and Hour of Discovery: May 9, 2013 A.M.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher, NMOCD	
By Whom? Bradley Blevins	Date and Hour: May 10, 2013 @ 1430 hrs	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse: Not Applicable	
If a Watercourse was Impacted, Describe Fully. * Not Applicable		

Depth to water? ~390 ft

**Describe Cause of Problem and Remedial Action Taken.\*** The release of approximately 160 barrels of produced water was the result of a lightning strike on a water tank; all fluid remained inside the firewall. A vacuum truck was utilized to recover any free liquids. An Emergency Response Team arrived at the release area and began continuous abatement of the impacted area.

**Describe Area Affected and Cleanup Action Taken.\*** Approximately 10,800 square feet of surface area within the confines of the berm was impacted by the release. Approximately 110 barrels of produced water was recovered from the site. Visibly stained soil was excavated and hauled away for disposal at a state approved facility. Soil samples were collected and submitted to Cardinal Laboratories for testing. Having received acceptable results and NMOCD approval, the affected area has been backfilled, and returned to proper conditions.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Bradley Blevins</i>		OIL CONSERVATION DIVISION	
Printed Name: Bradley Blevins		Approved by District Supervisor: <i>[Signature]</i>	
Title: HE Specialist	Approval Date: <i>3/4/10</i>	Expiration Date: <i>N/A</i>	
E-mail Address: bradley.blevins@chevron.com	Conditions of Approval: <i>Final</i>	Attached <input type="checkbox"/>	
Date: <i>7-30-13</i>	Phone: (575) 391-1462 ext. 86424	<i>approved per note</i>	

\* Attach Additional Sheets If Necessary

*in file that labs were seen  
& approved by environmental specialist*

*2RP-1687*