

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141

Revised August 8, 2011

MAR 28 2016

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1608940306

OPERATOR		<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Name of Company	Oxy Permian Ltd. <u>1106916</u>	Contact	Casey Summers
Address	6 Desta Drive, Midland, TX 79705	Telephone No.	(575) 513-8289
Facility Name	Pure Gold A Federal #2	Facility Type	Battery
Surface Owner	BLM	Mineral Owner	API No. 30-015-27243

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	21	23S	31E					Eddy

Latitude N 32.28449° Longitude W 103.78993°

NATURE OF RELEASE

Type of Release	Oil	Volume of Release	250 bbls	Volume Recovered	240 bbls
Source of Release	Valve on circulating pump was open	Date and Hour of Occurrence	<u>03/06/2016</u>	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher, Heather Patterson- NMOCD; Shelly Tucker- BLM		
By Whom?	Kathy Purvis @ BBC International Inc.	Date and Hour	03/07/2016 @ 2:13 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

Livestock kicked open the valve on a circulating pump causing 250 bbls of oil to spill inside the firewall. A vacuum truck recovered approximately 240 bbls of oil and the valve was closed.

Describe Area Affected and Cleanup Action Taken.\*

The affected area is approximately 75' x 60' inside the firewall. Remediation will be completed in accordance with an approved remediation plan from NMOCD and the BLM.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION	
Signature:	Approved by Environmental Specialist: <u>[Signature]</u>
Printed Name: Casey Summers	Approval Date: <u>3/29/16</u> Expiration Date: <u>N/A</u>
Title: NM Environmental Advisor	Conditions of Approval:
E-mail Address: Casey.Summers@oxy.com	Attached <input type="checkbox"/>
Date: <u>3-28-16</u> Phone: (575) 513-8289	Remediation per O.C.D. Rules & Guidelines

SUBMIT REMEDIATION PROPOSAL NO  
LATER THAN: 4/29/16

2RP-3623

\* Attach Additional Sheets If Necessary