

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

JUN 19 2013

Form C-141
Revised August 8, 2011

NMOC DISTRICT OFFICE IN
ARTESIA

Complete and submit to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NMLB/325238344

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: Cimarex Energy Company 162683	Contact: Johnny Tittsworth
Address: 600 N. Marienfield St. Suite 600 Midland, TX 79701	Telephone No. (432)-250-2059
Facility Name: Cottonwood Draw 22 Federal Com #1	Facility Type: Tank Battery

Surface Owner: Federal	Mineral Owner	API No. 30-015-36592
------------------------	---------------	----------------------

LOCATION OF RELEASE

Unit Letter P	Section 22	Township 25	Range 26	Feet from the 300	North/South Line South Line	Feet from the 793	East/West Line East Line	County Eddy
------------------	---------------	----------------	-------------	----------------------	--------------------------------	----------------------	-----------------------------	----------------

Latitude 32.11151 Longitudes -104.27439

NATURE OF RELEASE



Type of Release: Produced Water	Volume of Release: 15 barrels	Volume Recovered: 0 barrels
Source of Release: Well head	Date and Hour of Occurrence: 7/7/11	Date and Hour of Discovery
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Terry Ainsworth	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
BOP failed while fracing well, and fluid was released from well onto well pad.

Describe Area Affected and Cleanup Action Taken.*
Spill remained on location. Area will be sampled, and impacted soils will be remediated to work plan stipulations.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOC rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOC marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOC acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Johnny Tittsworth	Approved by Environmental Specialist: 	
Title: Environmental Compliance Coordinator	Approval Date: SEP 09 2013	Expiration Date:
E-mail Address: jtittsworth@cimarex.com	Conditions of Approval: Remediation proposal	Attached <input type="checkbox"/>
Date: 6/19/13	Phone: (432)-250-2059	

* Attach Additional Sheets If Necessary

Approved 9/9/13

2RP-1899