

NM OIL CONSERVATION
ARTESIA DISTRICT

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

APR 11 2016

Form C-141
Revised August 8, 2011

RECEIVED appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB 1610537909

OPERATOR		<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Name of Company Matador Resources		Contact Casey Snow	
Address 5400 LBJ Freeway Suite 1500 Dallas, TX. 75240		Telephone No. 972.371.5439	
Facility Name Zach McCormick #1		Facility Type Oil/Gas Well	
Surface Owner Roy Burkham		Mineral Owner	API No. 30-015-43654

LOCATION OF RELEASE

Unit Letter D	Section 18	Township 24 south	Range 29- east	Fect from the 716	North/South Line N	Fect from the 380	East/West Line W	County Eddy
-------------------------	----------------------	----------------------	----------------------	-----------------------------	------------------------------	-----------------------------	----------------------------	----------------

Latitude **32.22292** Longitude **104.030542**

NATURE OF RELEASE

Type of Release Water Based Mud	Volume of Release 20	Volume Recovered 19
Source of Release Gas Buster	Date and Hour of Occurrence	8pm 4-9-2016
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? n/a	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*
N/A

Describe Cause of Problem and Remedial Action Taken.*

Carry over on gas buster during drilling operations / Berm was created around spill area, vac. Truck flushed and removed water based mud

Describe Area Affected and Cleanup Action Taken.*

(Rock) well pad / Bermed contaminated area, flushed and removed mud

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOC rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOC marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOC acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		OIL CONSERVATION DIVISION	
Printed Name: Casey Snow		Approved by Environmental Specialist Mike Brumley	
Title: RES Coordinator		Approval Date: 4/14/16	Expiration Date: N/A
E-mail Address: csnow@matadorresources.com		Conditions of Approval:	
Date: 4-10-2016	Phone: 972.371.5439	Attached <input type="checkbox"/>	

Remediation per O.C.D. Rules & Guidelines

SUBMIT REMEDIATION PROPOSAL NO

LATER THAN: 5/14/16

2RP-3646

* Attach Additional Sheets If Necessary