

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

**NAB1611933379** **OPERATOR** ☒ Initial Report ☐ Final Report

Name of Company: BOPCO, L.P. <b>260737</b>	Contact: Amy Ruth
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: James Ranch Unit #12H	Facility Type: Exploration and Production
Surface Owner: Federal	Mineral Owner: Federal
API No. 30-015-22162	

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	21	22S	30E	1450	North	1830	East	Eddy

Latitude 32.380700° Longitude -103.884298°

**NATURE OF RELEASE**

Type of Release	Produced Water	Volume of Release	24 bbls	Volume Recovered	10 bbls
Source of Release	Line Failure from Jet Pump to Well	Date and Hour of Occurrence	4/21/2016 time unknown	Date and Hour of Discovery	4/21/2016 2:20 pm
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	N/A		
By Whom?	N/A	Date and Hour	N/A		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	N/A		

**NM OIL CONSERVATION**  
ARTESIA DISTRICT

**APR 27 2016**

**RECEIVED**

If a Watercourse was Impacted, Describe Fully.\*  
N/A



Describe Cause of Problem and Remedial Action Taken.\*

Collar on pressurized steel line corroded and fluids escaped to ground surface. Line was isolated and exposed. Line will be replaced.

Describe Area Affected and Cleanup Action Taken.\*

The leak affected 900 square feet of well pad. Standing fluids were recovered.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Amy C. Ruth	Approved by Environmental Specialist: 	
Title: EHS Remediation Specialist	Approval Date: <u>4/28/16</u>	Expiration Date: <u>N/A</u>
E-mail Address: ACRuth@basspet.com	Conditions of Approval: <input type="checkbox"/> Attached	
Date: 4/27/2016 Phone: 432-661-0571	<b>Remediation per O.C.D. Rules &amp; Guidelines</b>	

**SUBMIT REMEDIATION PROPOSAL NO**

**LATER THAN: 5/28/16**

**2RP-3662**

\* Attach Additional Sheets If Necessary