

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NABUW 2431874 OPERATOR ☒ Initial Report ☐ Final Report

Name of Company	Burnett Oil Co., Inc	Contact	Leslie Garvis
Address	801 Cherry Street, Ste 1500, Fort Worth, Texas 76102	Telephone No.	817-583-8730
Facility Name	Jackson B 30	Facility Type	WIW
Surface Owner	BLM	Mineral Owner	BLM
		API No.	30-015-21386

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
N	1	17S	30E	660	South	1980	West	Eddy

Latitude 32.85804 Longitude -103.92752

NATURE OF RELEASE

Type of Release	Oil/Water	Volume of Release	3 BO/57 BW	Volume Recovered	0 BO/0 BW
Source of Release	Steel injection line corroded & released fluid	Date and Hour of Occurrence		Date and Hour of Discovery	4/28/16/0800
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Phone Call to BLM - S. Tucker, OCD - H. Patterson		
By Whom?	Leslie Garvis	Date and Hour	4/28/16 approx 1500		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	N/A		
If a Watercourse was Impacted, Describe Fully.* N/A					
Describe Cause of Problem and Remedial Action Taken.* Steel Injection line corroded and release fluid. Line has been repaired and put back into service.					
Describe Area Affected and Cleanup Action Taken.* Please see attached diagram for description of areas on and off the pad that were impacted. The impacted area will be assessed and remediated per regulatory standards.					
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.					

NM OIL CONSERVATION  
ARTESIA DISTRICT  
MAY 02 2016  
RECEIVED

Signature	<u>Leslie Garvis</u>		
Printed Name:	Leslie Garvis	Approved by Environmental Specialist <u>H. Patterson</u>	
Title:	Regulatory Coordinator	Approval Date:	5/3/16
E-mail Address:	lgarvis@burnettoil.com	Expiration Date:	N/A
Date:	5/2/16	Phone:	817-583-8730
		Conditions of Approval:	Attached <input type="checkbox"/>
		Remediation per O.C.D. Rules & Guidelines	

\* Attach Additional Sheets If Necessary

SUBMIT REMEDIATION PROPOSAL NO 2RP-3670  
LATER THAN: 6/3/16