

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
40 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company – Corkran Energy	Contact – Dennis Corkran
Address – 300 Beardsley Lane C204 Austin, TX 78746	Telephone No. – 512-329-6140
Facility Name – Orleans 25 #1	Facility Type – Drilling Pit
Surface Owner – Private	Mineral Owner –
Lease No. 30-015-35260	

LOCATION OF RELEASE

Unit Letter B	Section 25	Township 18S	Range 26E	Feet from the North/South Line	Feet from the East/West Line	County Eddy
------------------	---------------	-----------------	--------------	-----------------------------------	---------------------------------	----------------

Latitude 32° 43.444' N Longitude 104° 19.923' W

NATURE OF RELEASE



Type of Release – Drilling Pit Contents	Volume of Release – N/A	Volume Recovered – N/A
Source of Release – Drilling Pit	Date and Hour of Occurrence NA	Date and Hour of Discovery 9-24-09
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* Drilling pit contents leaked into underlying soil.

Describe Area Affected and Cleanup Action Taken.* Pit bottoms were tested and delineated to NMOCD standards. Attached is a plat map, field analytical and lab confirmations of the delineation. The approved remediation plan was completed. The impacted soil was excavated at the following areas: TP1, TP2, TP3 and TP4 was excavated to 10' bgs and TP5 was excavated to 20' bgs. The impacted soil was excavated and hauled to Lea Land Disposal. The site was backfilled and seeded per the original pit closure plan.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: <u>DENNIS CORKRAN, PRESIDENT</u>		Approved by District Supervisor: 	
Title: <u>HUMMINGBIRD INVESTMENTS, LLC, C.P.</u>		Approval Date: <u>5/13/10</u>	Expiration Date: <u>N/A</u>
Email Address: <u>D.CORKRAN@CORKRANENERGY.COM</u>		Conditions of Approval: <u>Final</u>	
Date: <u>10/18/09</u> Phone: <u>512-329-6140</u>		Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

22P-343