**NM OIL CONSERVATION** ARTESIA DISTRICT

District 1 1625 N. French Dr., Hobbs, NM 88240 District 11 811 S. First St., Artesia, NM 88210 District 111 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

١

State of New Mexico **Energy Minerals and Natural Resources** 

> **Oil Conservation Division** 1220 South St. Francis Dr. Santa Fe, NM 87505

MAY 1 6 2016 Form C-141 Revised August 8, 2011

Submipropropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action														
NAB 1613949519						OPERATOR				🛛 Initial Report 🗌 Final Repor				
Name of Co	31	Contact:				Robert McNeill								
Address:	Telephone No.         432-683-7443													
Facility Name: COTTONWOOD 36 STATE SWD #001						Facility Type: SWD								
Surface Owner: State Mineral Owner						·				API No. 30-015-29560				
LOCATION OF RELEASE														
Unit Letter K	Section 35	Township 25S	Range 26E	Feet from the 1980	Nort	h/South Line	i	from the		Vest Line		County Eddy		
<u> </u>							iuy							
Latitude 32.0844536 Longitude 104.2486954														
NATURE OF RELEASE														
Type of Relea Produced Wa	Volume of Release: 5bbls of Produced Water				Volume Recovered: 3bbls of Produced Water									
Source of Release:						Date and Hour of Occurrence:				Date and Hour of Discovery:				
	Injection Well						05-06-2016 11:00am				05-06-2016 11:00am			
Was Immedia	ate Notice C		Yes 🛛	No 🛛 Noi Re	If YES, To Whom?									
By Whom?						Date and Hour:								
Was a Watercourse Reached?						If YES, Volume Impacting the Watercourse.								
🗌 Yes 🖾 No														
If a Watercou	irse was Im	pacted, Descri	ibe Fully.'	•				·						
Describe Cause of Problem and Remedial Action Taken.*														
The threading on the collar above the master valve washed out. Replaced the collar on the wellhead.														
Describe Area Affected and Cleanup Action Taken.*														
The release c	oused a 20'	X 5° staining	on the pa	d by the wellhead	. Cone	ho has replace	d the co	llar on the	: wellhe	ad and will	have the sp	ill sit	e sampled to	
The release caused a 20' X 5' staining on the pad by the wellhead. Concho has replaced the collar on the wellhead and will have the spill site sampled to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant														
remediation work.														
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and														
regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability														
should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other														
federal, state,	or local la	ws and/or regu	lations.						0501		DUVICI	227		
Signature: Robert Amer L					OIL CONSERVATION DIVISION									
Printed Name: Robert Grubbs Jr.						Approved by Environmental Speinter 11/4 Demonster								
Printed Name	e:	Rober	l Grubbs J	Ir.		Approved by	Enviro	nmental S	počialis	<u> 11/4 /</u>	SRH CAL	<u>×_</u>		
Title:	S	enior Environ	mental Co	ordinator		Approval Da	1e:5/	17/11	6	Expiration	Date: N	1A		
E mail Adda		man.hka/2	oonaha -			Conditions	<u>с ланан</u>							
E-mail Addro	:55:	rgrubbs(d	concho.co	1110		Conditions o Remedia	i Appro tion n	er O.C.	D. Rui	es & Gu	idelines	I 🗆	Ì	
Date:	05-16-201		Phor	ne: 432-683-74	143	SUBMIT	REME	DIATIO	NPR	<u>QPOSAL</u>	<u>. NO</u>			
<ul> <li>Attach Addi</li> </ul>	tional She	ets If Necess	агу			LATER T			ИТ	16		2RF	2.3695	