

# NM OIL CONSERVATION

ARTESIA DISTRICT

JUN 07 2016

Form C-141  
Revised August 8, 2011

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in  
conformance with 19.15.29 NMAC.

RECEIVED

## Release Notification and Corrective Action

**NAB/6160.541052** **229137**

<b>OPERATOR</b>		<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Name of Company: COG Operating LLC		Contact: Robert McNeill	
Address: 600 West Illinois Avenue, Midland TX 79701		Telephone No. 432-230-0077	
Facility Name: WILLOW 17 STATE SWD #001		Facility Type: SWD	
Surface Owner: State		Mineral Owner:	
		API No. 30-015-41806	

## LOCATION OF RELEASE

Unit Letter P	Section 17	Township 25S	Range 28E	Feet from the 660'	North/South Line South	Feet from the 660'	East/West Line East	County Eddy
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude 32.1243935 Longitude -104.1029892

## NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 15 bbls PW	Volume Recovered: 0 bbls PW
Source of Release: Flowline	Date and Hour of Occurrence: 5/27/2016 Unknown	Date and Hour of Discovery: 5/27/2016 2:00 pm
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* This release was caused by a check valve on a poly flowline. The broken check valve was replaced.		
Describe Area Affected and Cleanup Action Taken.* This release occurred in the pasture on the north edge of the facility and is approximately 0.1 acre in size. Concho will have the spill site sampled to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: <u>Robert L. McNeill</u>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Robert McNeill	Signed By: <u>Mike Brannan</u> Approved by Environmental Specialist:	
Title: Environmental Manager	Approval Date: <u>6/8/16</u>	Expiration Date: <u>N/A</u>
E-mail Address: rmccneill@concho.com	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines <input type="checkbox"/> Attached <input type="checkbox"/>	
Date: June 6, 2016 Phone: 432-230-0077	SUBMIT REMEDIATION PROPOSAL NO <u>114110</u>	

\* Attach Additional Sheets If Necessary

LATER THAN: 114110

ARP-3721