District I 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

100

## State of New Mexico Energy Minerals and Natural Resources

**Oil Conservation Division** 1220 South St. Francis Dr. Santa Fe, NM 87505

## NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141 Revised August 8, 2011

JUN 1 0 2016 Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action						
NAB1616633908		OPERATOR	$\boxtimes$	Initial Report		Final Report
Name of Company	• <b></b>	Contact		·		
Yates Petroleum Corporation	5575	Amber Griffin				
Address		Telephone No.				
105 S. 4th Street Artesia, NM 88210		575-748-1471				
Facility Name		Facility Type				
Satchmo SWD State #1		Well/Tanks				
Surface Owner	Mineral Owner	······································		PINo		

I	Surface Owner	Indiat Owner	ALTINO,
	State	State	30-015-42492
			······································

LOCATION OF RELEASE								
Unit Letter	Section	Township	Range	Feet from the 330	North/South Line	Feet from the	East/West Line	County
B	36	25S	31E		North	1980	East	Eddy

Latitude 32.09297 Longitude 103.72897

NATURE OF RELEASE						
Type of Release	Volume of Release	Volume Recovered				
Produced water	15 B/PW	10 B/PW				
Source of Release	Date and Hour of Occurrence	Date and Hour of Discovery				
8" poly line	6/3/2016; PM	6/3/2016; PM				
Was Immediate Notice Given?	If YES, To Whom?					
Yes No 🕅 Not Required						
By Whom?	Date and Hour					
Was a Watercourse Reached?	If YES, Volume Impacting the Wa	atercourse.				
🗌 Yes 🖾 No						
If a Watercourse was Impacted, Describe Fully.* N/A						
Describe Cause of Problem and Remedial Action Taken.*						
An 8" poly line from the H pump to the booster pump ruptured. Valves a	upstream and downstream were closed	i, the water pump was turned off and the				
water line was isolated.						
Describe Area Affected and Cleanup Action Taken.						
The affected area was inside the lined/bermed battery, along parts of the	east and south side of the location and	I an 18' x 10' area off of the production pad.				
The release area was scraped and soils were hauled to a NMOCD approved facility. Vertical and horizontal delineation samples will be taken from the						
release area and analysis will be run for TPH & BTEX (chlorides for doc	umentation). If initial analytical resu	Its for TPH & BTEX are under RRAL's (site				
ranking is 0) a Final Report, C-141 will be submitted to the OCD requesting closure. If the analytical results are above the RRAL's a work plan will be						
submitted to the OCD. Depth to Ground Water: >100' (approximately 300', per Chevron/Texaco Trend Map), Weilhead Protection Area: No,						
Distance to Surface Water Body: >1000', SITE RANKING IS 0.						
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger						
regulations an operators are required to report and/or the certain release the sublic health of the environment. The presentance of $p \in [14]$ report by the	nouncations and perform corrective a	t does notlight the suggestion of lightlight				
public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability						
should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other						
federal, state, or local laws and/or regulations.						
	OIL CONSERVATION DIVISION					
()  ()  ()  ()  ()		<u>Introduction</u>				
Signature: UNDEL Drug Kin						
Printed Name: Amber Griffin Approved by Environmental Specialist:						
						talutter MA
Title: Environmental Representative	Approval Date: U14/10	Expiration Date: N/P1				
E-mail Address: agriffin@yatespetroleum.com	Conditions of Approval:					
E-mail Address: agriffin@yatespetroleum.com Conditions of Approval:   Date: June 10, 2016 Phone: 575-748-4111   Attach Additional Sheets If Necessary Conditions of Approval:						
Date: June 10, 2016 Phone: 575-748-4111	28P DANT DEMEDIATION P	ROPOSAL NO				
* Attach Additional Sheets If Necessary		110 100 2121				
· · ··································	ATER THAN:	AKP-2120				