

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141
Revised August 8, 2011

JUN 16 2016

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1616930688

66137

OPERATOR

☒ Initial Report

☒ Final Report

Name of Company Devon Energy Production Company	Contact Danny Velo, Production Foreman
Address 6488 Seven Rivers Hwy Artesia, NM 88210	Telephone No. 575-703-3360
Facility Name Parkway West SWD #1	Facility Type Salt Water Disposal

Surface Owner State	Mineral Owner State	API No 30-015-42687
---------------------	---------------------	---------------------

LOCATION OF RELEASE

Unit Letter D	Section 27	Township 19S	Range 29E	Feet from the 1255	North/South Line North	Feet from the 430	East/West Line West	County Eddy
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	----------------------	------------------------	----------------

Latitude: 32.6354904 Longitude: -104.0698929

NATURE OF RELEASE

Type of Release Produced water	Volume of Release 10 BBLS	Volume Recovered 10 BBLS
Source of Release Discharge pump line	Date and Hour of Occurrence 6/13/2016 @ 9:25pm	Date and Hour of Discovery 6/13/2016 @ 9:25pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? OCD-Mike Bratcher	
By Whom? David Simmons, Assistant Production Foreman	Date and Hour OCD- 6/13/2016 @ 9:35pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse N/A	

If a Watercourse was Impacted, Describe Fully.* N/A


Describe Cause of Problem and Remedial Action Taken.*

Corrosion occurred in the water discharge pump line resulting in a release of 10 BBLS produced water. The well and water injection pump was shut down immediately to prevent further release. Repairs to discharge pump line are in progress.

Describe Area Affected and Cleanup Action Taken.*

10 BBLS of produced water was released from a corroded discharge pump line that runs from the produced water tanks. All 10 BBLS of produced water released remained in concrete containment. None of the released fluid left location. Vacuum truck recovered all 10 BBLS of the released produced water. No further action is necessary.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Sarah Gallegos-Troublefield	OIL CONSERVATION DIVISION		
Printed Name: Sarah Gallegos-Troublefield	Approved by Environmental Specialist: 		
Title: Field Admin Support	Approval Date: 6/17/16	Expiration Date: N/A	
E-mail Address: Sarah.Gallegos-Troublefield@dm.com	Conditions of Approval: FINAL		Attached <input type="checkbox"/>
Date: 6/16/2016 Phone: 575.748.1864			

* Attach Additional Sheets If Necessary

2RD-3746