

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141
Revised August 8, 2011

JUN 23 2016

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Cimarex Energy	Contact	Christine Alderman
Address	600 N Marienfeld Ste 600 Midland TX	Telephone No.	432-853-7059
Facility Name	Crow Flats 16 State #2	Facility Type	Production
Surface Owner	Mineral Owner	API No. 30-015-35556	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	16	16S	28E	660	S	330	W	Eddy

Latitude 32.91713 Longitude -104.18829

NATURE OF RELEASE

Type of Release	crude oil	Volume of Release	165 bbls	Volume Recovered	85 bbls
Source of Release	steel tank	Date and Hour of Occurrence	6/20/2016	Date and Hour of Discovery	6/20/2016
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher/Heather Patterson		
By Whom?	Christine Alderman	Date and Hour	6/21/2016 1:08pm	*via e-mail	
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully:

Describe Cause of Problem and Remedial Action Taken.
The crude oil stock tank developed a hole in the bottom of it.

Describe Area Affected and Cleanup Action Taken.
The tank battery is lined with plastic liner and thick gravel. While recovering fluids a tear was noticed in the liner.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Christine Alderman	OIL CONSERVATION DIVISION	
Printed Name: Christine Alderman	Approved by Environmental Specialist:	
Title: ESH Supervisor	Approval Date: 6/23/16	Expiration Date: N/A
E-mail Address: calderman@cimarex.com	Conditions of Approval:	
Date: 6/23/2016 Phone: 432-853-7059	Remediation per O.C.D. Rules & Guidelines SUBMIT REMEDIATION PROPOSAL NO	

* Attach Additional Sheets If Necessary

LATER THAN:

7/27/16 ARP-3755