

NM OIL CONSERVATION

ARTESIA DISTRICT

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

JUL 01 2016

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
conformance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

0AB1618834549

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: COG Operating LLC 229137	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-683-7443
Facility Name: REALLY SCARY FEDERAL COM #003H	Facility Type: Battery
Surface Owner: Fee	Mineral Owner: Federal
API No. 30-015-36372	

LOCATION OF RELEASE

Unit Letter N	Section 33	Township 24S	Range 28E	Feet from the 430'	North/South Line South	Feet from the 2310'	East/West Line West	County Eddy
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	------------------------	------------------------	----------------

Latitude/Longitude 32.1677322,-104.0935135

NATURE OF RELEASE

Type of Release: Oil	Volume of Release: 92 bbls Oil	Volume Recovered: 87 bbls Oil
Source of Release: Valve on circulating pump	Date and Hour of Occurrence: 6/27/2016 unknown	Date and Hour of Discovery: 6/27/2016 10:30 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher - NMOCD / Shelly Tucker - BLM	
By Whom? Amanda Trujillo Davis	Date and Hour: Mon, Jun 27, 2016 at 7:54 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

This release was caused by an open valve on a circulating pump. Vacuum trucks were dispatched to recover all standing fluid.

Describe Area Affected and Cleanup Action Taken.*

This release was contained within the lined containment. Concho will have the spill site inspected for any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Amanda T. Davis</i>	OIL CONSERVATION DIVISION	
Printed Name: Amanda Trujillo Davis	Approved by Environmental Specialist <i>[Signature]</i>	
Title: Senior Environmental Coordinator	Approval Date: 7/16/16	Expiration Date: N/A
E-mail Address: atrujillo@concho.com	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines Attached <input type="checkbox"/>	
Date: June 30, 2016 Phone: 575-748-6940	SUBMIT REMEDIATION PROPOSAL NO. 817116	

* Attach Additional Sheets If Necessary

LATER THAN: 8/7/16

2RP-3759