

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION
ARTESIA DISTRICT

JULY 15, 2016

RECEIVED

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

REVISED

Release Notification and Corrective Action

NAB1620034005

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company	Chevron USA Inc. 4323	Contact	Josepha DeLeon
Address	15 Smith Rd, Midland, TX.	Telephone No.	575-263-0424 Cell - 432-425-1528
Facility Name	IMC 21 FEDERAL COM No. 002H	Facility Type	Oil Well

Surface Owner	Mineral Owner	API No's.
		3001536109

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	21	23S	29E					Eddy

Latitude 32.296460 N Longitude -103.982034 W

NATURE OF RELEASE

Type of Release	Spill	Volume of Release	10.1 BW; .58 BO (in containment) .85 BW; .09 BO spray outside containment.	Volume Recovered	10.68 Total Fluid Recovered
Source of Release:	PSV popped and release pressure and spill of fluid	Date and Hour of Occurrence	07/14/2016; 8:00 AM	Date and Hour of Discovery	07/14/2016; 12:00 PM
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Phone Call to Amalia Bustamante (NMOCD) Jim Amos (BLM)			
By Whom?	Josepha DeLeon	Date and Hour	07/15/2016 06:00 AM		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*



Plugged/failure of oil and water dump valves on the separator leading the PSV to POP and release pressure along with water and oil in secondary containment with minor mist outside containment.

Isolated well and called vacuum truck to remove liquids.

Describe Area Affected and Cleanup Action Taken.*

Microbes for overspray to pasture.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION		
Printed Name: Josepha DeLeon	Approved by Environmental Specialist: 		
Title: HES Compliance Support - Environmental	Approval Date: 7/18/16	Expiration Date: N/A	
E-mail Address: jdxdc@chevron.com	Conditions of Approval: FINAL		Attached <input type="checkbox"/>
Date: 05/06/2016	Phone: 575-263-0424		

* Attach Additional Sheets If Necessary

2RP 3183