

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141

Revised August 8, 2011

JUL 13 2016

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

DAB1019735083 OPERATOR ☒ Initial Report ☒ Final Report

Name of Company	Oxy Permian Ltd.	Contact	Casey Summers
Address	6 Desta Drive, Midland, TX 79705	Telephone No.	(575) 513-8289
Facility Name	Cypress 33 Federal #2H Battery	Facility Type	Battery
Surface Owner	BLM	Mineral Owner	
		API No.	30-015-37308

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	33	23S	29E					Eddy County, NM

Latitude N 32.26673°

Longitude W 103.98348°

NATURE OF RELEASE

Type of Release	Oil	Volume of Release	8 bbls	Volume Recovered	7.5 bbls
Source of Release	A power failure caused the tank to overflow	Date and Hour of Occurrence	04/22/2016	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher, Heather Patterson- NMOCD; Shelly Tucker-BLM		
By Whom?	Kathy Purvis @ BBC International Inc.	Date and Hour	04/25/2016 @ 10:43 am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*


Describe Cause of Problem and Remedial Action Taken.\*

A power failure caused a tank to overflow and leak 8 bbls of oil. A vacuum truck recovered 7.5 bbls of oil and the power was restored.

Describe Area Affected and Cleanup Action Taken.\*

The affected area is approximately 14' x 14' inside the lined containment. Remediation was completed removing the contaminated material and replacing it with clean material.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	<u>OIL CONSERVATION DIVISION</u>		
Printed Name: Casey Summers	Approved by Environmental Specialist: 		
Title: NM Environmental Advisor	Approval Date: 7/14/16	Expiration Date: N/A	
E-mail Address: casey_summers@oxy.com	Conditions of Approval: FINAL		Attached <input type="checkbox"/>
Date: 7-11-16	Phone: (575) 513-8289		

\* Attach Additional Sheets If Necessary

2RP-3778