

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

JUL 19 2016

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

0AB1620451784

OPERATOR		<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Name of Company:	COG Operating LLC <i>224137</i>	Contact:	Robert McNeill
Address:	600 West Illinois Avenue, Midland TX 79701	Telephone No.	432-683-7443
Facility Name:	CLUSTER STATE COM #001H	Facility Type:	Flowline
Surface Owner:	State	Mineral Owner:	API No. 30-015-37547

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	16	26S	27E	380'	North	330'	West	Eddy

Latitude 32.0486679 Longitude 104.2026672

NATURE OF RELEASE

Type of Release:	Produced Water	Volume of Release:	10bbls of Produced water	Volume Recovered:	0bbls of Produced water
Source of Release:	Poly Flowline	Date and Hour of Occurrence:	07-16-2016 09:00am	Date and Hour of Discovery:	07-16-2016 09:00am
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?		Date and Hour:			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Polyline failure. Cut out bad section of line and refuse the poly line back together.

Describe Area Affected and Cleanup Action Taken.*

This spill affected an area of 2' x 100' and 12' x 10' in the pasture, Concho will have the spill site sampled to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION	
Signature:	<i>Robert Grubbs Jr.</i>
Printed Name:	Robert Grubbs Jr.
Title:	Senior Environmental Coordinator
E-mail Address:	rgrubbs@concho.com
Date:	July 19, 2016
Phone:	432-683-7443
Approved by Environmental Specialist: <i>[Signature]</i>	
Approval Date: <i>7/21/16</i> Expiration Date: <i>N/A</i>	
Conditions of Approval:	
Remediation per O.C.D. Rules & Guidelines <input type="checkbox"/>	
SUBMIT REMEDIATION PROPOSAL NO	
LATER THAN: <i>7/25/16</i>	

* Attach Additional Sheets If Necessary

220-3792