

State of New Mexico
Energy, Minerals and Natural Resources Department

Susana Martinez
Governor

David Martin
Cabinet Secretary

Tony Delfin
Deputy Cabinet Secretary

David Catanach, Director
Oil Conservation Division



Response Required - Deadline Enclosed

*Field Inspection Program
"Preserving the Integrity of Our Environment"*

22-Jul-16

TANDEM ENERGY CORPORATION
2700 POST OAK BLVD SUITE 1000
HOUSTON TX 77056

LETTER OF VIOLATION - Inspection

Dear Operator:

The following inspection(s) indicate that the well, equipment, location or operational status of the well(s) failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date(s) indicated.

Please notify the proper district office of the Division, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.


INSPECTION DETAIL SECTION

BALLARD GRAYBURG SAN ANDRES UNIT No.003				C-5-18S-29E	30-015-03295-00-00		
Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.	
07/22/2016	Routine/Periodic	Tony Morales	Yes	No	10/25/2016	iTM1620437944	
Violations General Housekeeping (Rule 114)							
Comments on Inspection: OK. All Equipment and Location in Good Shape. PJ, STAINING AROUND WELL HEAD							
BALLARD GRAYBURG SAN ANDRES UNIT No.001B				M-5-18S-29E	30-015-03303-00-00		
Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.	
07/22/2016	Routine/Periodic	Tony Morales	Yes	No	10/25/2016	iTM1620434589	
Violations General Housekeeping (Rule 114)							
Comments on Inspection: OK. All Equipment and Location in Good Shape. PJO. STAINING AROUND WELL HEAD.							

BALLARD GRAYBURG SAN ANDRES UNIT No.001D				E-5-18S-29E	30-015-03304-00-00	
Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
07/22/2016	Routine/Periodic	Tony Morales	Yes	No	10/25/2016	iTM1620438748
Violations General Housekeeping (Rule 114)						
Comments on Inspection: OK. All Equipment and Location in Good Shape. PJ. STAINING AROUND WELL HEAD.						
BALLARD GRAYBURG SAN ANDRES UNIT No.002C				N-5-18S-29E	30-015-03306-00-00	
Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
07/22/2016	Routine/Periodic	Tony Morales	Yes	No	10/25/2016	iTM1620435473
Violations General Housekeeping (Rule 114)						
Comments on Inspection: OK. All Equipment and Location in Good Shape. PJ. STAINING AROUND WELL HEAD.						
BALLARD GRAYBURG SAN ANDRES UNIT No.004B				J-5-18S-29E	30-015-20975-00-00	
Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
07/22/2016	Routine/Periodic	Tony Morales	Yes	No	10/25/2016	iTM1620439439
Violations Absent Well Identification Signs (Rule 103)						
Comments on Inspection: OK. All Equipment and Location in Good Shape. LOCATION SIGN NOT VISIBLE						
BALLARD GRAYBURG SAN ANDRES UNIT No.006A				C-5-18S-29E	30-015-24117-00-00	
Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
07/22/2016	Routine/Periodic	Tony Morales	Yes	No	10/25/2016	iTM1620437742
Violations General Housekeeping (Rule 114)						
Comments on Inspection: OK. All Equipment and Location in Good Shape. PJO, STAINING AROUND WELL HEAD.						
TRAVIS E FEDERAL No.001				K-6-18S-29E	30-015-24486-00-00	
Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
07/22/2016	Routine/Periodic	Tony Morales	Yes	No	10/25/2016	iTM1620444731
Violations Fire Walls and Dikes						
Comments on Inspection: OK. All Equipment and Location in Good Shape. PJ. TANK BATTERIES NO CONTAINMENT.						
BALLARD GRAYBURG SAN ANDRES UNIT No.005T				P-6-18S-29E	30-015-36201-00-00	
Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
07/22/2016	Routine/Periodic	Tony Morales	Yes	No	10/25/2016	iTM1620447352
Violations Absent Well Identification Signs (Rule 103)						
Comments on Inspection: OK. All Equipment and Location in Good Shape. PJ. WRONG API # SHOWS 30-015-34658, SHOULD BE 30-015-36201.						
BALLARD GRAYBURG SAN ANDRES UNIT No.003T				H-6-18S-29E	30-015-36204-00-00	
Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
07/22/2016	Routine/Periodic	Tony Morales	Yes	No	10/25/2016	iTM1620448262
Violations Absent Well Identification Signs (Rule 103)						
Comments on Inspection: OK. All Equipment and Location in Good Shape. PJ See API no.34659. Well sign has Api no.30-015-34659 .A cancelled APD. SHOULD BE API 30-015-36204.						

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Division Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well.

Sincerely,



Artesia OCD District Office

Note: Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data.
*Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas.