

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

AUG 03 2016

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
RECEIVED accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

**NAB1621833103**

OPERATOR		<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Name of Company:	COG Operating LLC <b>229137</b>	Contact:	Robert McNeill
Address:	600 West Illinois Avenue, Midland TX 79701	Telephone No.	432-685-4304
Facility Name:	SRO STATE COM #018H	Facility Type:	Tank Battery
Surface Owner:	State	Mineral Owner:	API No. 30-015-39999

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	17	26S	28E	330'	North	330'	East	Eddy

Latitude 32.0488815 Longitude -104.1021042

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 5bbls of Produced Water	Volume Recovered: 4bbls of Produced Water
Source of Release: Sight Glass	Date and Hour of Occurrence: 07-24-2016 1:00 pm	Date and Hour of Discovery: 07-24-2016 1:00 pm
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.*  The release was caused a sight glass failed. Replace the sight glass.		
Describe Area Affected and Cleanup Action Taken.*  This release occurred within a lined facility. A vacuum truck was dispatched to remove all freestanding fluids. Concho will have the spill area evaluated for any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

Signature:		OIL CONSERVATION DIVISION	
Printed Name:	Robert Grubbs Jr.	Approved by Environmental Specialist:	<i>[Signature]</i>
Title:	Senior Environmental Coordinator	Approval Date:	8/5/16
E-mail Address:	rgrubbs@concho.com	Expiration Date:	N/A
Date:	August 3, 2016	Phone:	432-685-4304
		Conditions of Approval: Remediation per O.C.D. Rules & Guidelines	<input type="checkbox"/>
		SUBMIT REMEDIATION PROPOSAL NO	

\* Attach Additional Sheets If Necessary.

LATER THAN: **9/8/16**

**2RP-3818**