

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141

Revised August 8, 2011

AUG 12 2016

Submit Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

DABI/223839080 OPERATOR ☒ Initial Report ☐ Final Report

Name of Company:	COG Operating LLC	Contact:	Robert McNeill
Address:	600 West Illinois Avenue, Midland TX 79701	Telephone No.	432-683-7443
Facility Name:	BULLSEYE 22 STATE COM #001H	Facility Type:	Tank Battery
Surface Owner:	State	Mineral Owner:	API No. 30-015-40162

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	22	24S	27E	330'	North	990'	West	

Latitude 32.2091255 Longitude 104.1840591

NATURE OF RELEASE

Type of Release: Oil and Produced Water	Volume of Release: 14bbls of Oil / 2bbls of Produced Water	Volume Recovered: 14bbls of Oil / 2bbls of Produced Water
Source of Release: Hole in Separator	Date and Hour of Occurrence: 08-05-2016 07:20 am	Date and Hour of Discovery: 08-05-2016 07:20 am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* A hole developed in the separator due to age. The separator will be repaired tested and put back into operation.		
Describe Area Affected and Cleanup Action Taken.* The release was contained within a lined facility. A vacuum truck was dispatched to remove all freestanding fluids. The containment will be cleaned and the facility will be put back into operation. Concho will have the spill site inspected for any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

Signature: <u>Robert Grubbs Jr.</u>	OIL CONSERVATION DIVISION	
Printed Name: Robert Grubbs Jr.	Approved by Environmental Specialist: <u>[Signature]</u>	
Title: Senior Environmental Coordinator	Approval Date: <u>8/15/16</u>	Expiration Date: <u>NIA</u>
E-mail Address: <u>rgrubbs@concho.com</u>	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines <input type="checkbox"/> Attached <input type="checkbox"/>	
Date: August 12, 2016 Phone: 432-683-7443	SUBMIT REMEDIATION PROPOSAL NO <u>4115116</u>	

* Attach Additional Sheets If Necessary

LATER THAN: 4115116

2RP-3833